Radiogram 7019u Form 24 for 12/04/03 PLASMA CRYSTAL-3 (TV Downlink).

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40	CDR	Post-sleep
06:10-06:15	FE-1	PLASMA CRYSTAL-3: Turbo-pump activation
06:15-06:40	FE-1	Post-sleep
06:40-07:30		BREAKFAST
07:30-08:00		Prep for work
08:00-08:05	CDR	SSC reboot (start)
08:15-08:30		DPC (S-band)
08:30-08:35	CDR	SSC reboot (completion)
08:30-11:30	FE-1	Water transfer from Rodnik tank 5B2 in Progress to EDV
08:35-09:05	CDR	TWIS bungee inspection
09:35-10:05	CDR	Transfer of TWIS accelerometer
10:15-11:45	CDR	Physical Exercise (RED)
11:30-12:55	FE-1	Physical Exercise (VELO + Load Training) day1
11:45-12:15	CDR	СОЖ maintenance
12:15-12:45	CDR	IWIS installation
12:45-12:55	CDR	PAO equipment set up
12:55-13:55		LUNCH
13:55-14:25	FE-1	PLASMA CRYSTAL -3. Experiment set up. Tag up (S-band)
13:55-14:05	CDR	EMU battery charge (completion)
14:05-14:35	CDR	SSC config for EMU batteries ops
14:25-15:00	FE-1	TV downlink. PLASMA CRYSTAL. Experiment (start). Tag up (S-band)
14:35-14:45	CDR	PAO prep
14:45-15:05	CDR	BBC program Breakfast with (Sir David) Frost (Ku+ S-band)
15:05-15:25	CDR	EMU battery discharge
15:05-15:15	FE-1	Installation of IWIS RSU
15:15-15:35	FE-1	IMS file prep
15:25-15:55	CDR	SSC4 laptop nominal reconfig
15:50-16:00	FE-1	PLASMA CRYSTAL -3. Experiment (completion).
16:00-18:30		TVIS: troubleshooting
18:30-18:40	CDR	IWIS battery power off
18:30-18:40	FE-1	Removal of IWIS RSU
18:40-18:55		Daily plan review
18:55-19:15		Prep for work
19:15-19:30		DPC (S-band)
19:30-20:00		DINNER (RENAL: pill ingestion)
20:00-20:30		Daily food prep
20:30-21:25		Pre-sleep
21:25-21:30	FE-1	PLASMA CRYSTAL -3. Turbo-pump deactivation
21:30-06:00		SLEEP
Task list	FE-1	Search for equipment

Note: See OSTP for references to US activities.

End of radiogram