Radiogram No. 2764u Form 24 for 07/02/2013 RECS Check in Refueling Configuration. ВД-СУ Mode Deactivation/Activation And БИТС Power Off/On

TIME	CREW	ACTIVITY
06:00-07:00	CDR	SPRUT-2. Experiment Ops
06:00-06:10	FE-2	Morning Inspection. SM ΠCC (Caution & Warning Panel) Test Laptop RS2(1) Reboot RSS1, RSS2 Reboot
06:00-06:10	FE-3, FE-5, FE-6	Morning Inspection.
06:00-06:15	FE-4	KHROMATOMASS. Experiment Setup
06:10-06:20	FE-2	Hematocrit Test
06:10-06:20	FE-5	Post-Sleep
06:10-06:40	FE-3, FE-6	Post-Sleep
06:15-06:45	FE-4	KHROMATOMASS. Saliva and Blood Collection
06:20-06:30	FE-5	Hematocrit Test
06:20-06:50	FE-2	Post-Sleep
06:30-06:50	FE-5	Post-Sleep
06:40-07:30	FE-3, FE-6	BREAKFAST.
06:45-06:55	FE-4	Hematocrit Test
06:50-07:40	FE-2 , FE-5	BREAKFAST.
06:55-07:25	FE-4	Post-Sleep
07:00-07:10	CDR	Hematocrit Test
07:10-07:15	CDR	Hematocrit. Hardware Stowage
07:15-07:45	CDR	Post-Sleep
07:25-08:10	FE-4	BREAKFAST.
07:30-07:45	FE-3	Work Prep
07:30-07:50	FE-6	Work Prep
07:40-08:00	FE-2	Work Prep
07:40-08:10	FE-5	Work Prep
07:45-08:10	FE-3	On-orbit hearing assessment using EARQ
07:45-08:10	CDR	BREAKFAST.
08:00-08:10	FE-2	BKC Laptops Antivirus Scan Check and Status Report
08:10-08:35	-	Daily Planning Conference (S-band)
08:35-09:50	FE-2	Configuring ΠxO and CO1 to Initial State after EVA
08:35-09:30	FE-4	MAI-75 Hardware Setup and Activation. Tagup with specialists (Sband)
08:35-10:00	FE-5	ATV Cargo Operations
08:35-08:45	FE-6	CIR - Hardware Setup
08:35-10:00	FE-3	ATV Cargo Operations
08:35-09:10	CDR	BREAKFAST.

08:45-09:45	FE-6	Physical Exercise (T2)
09:10-09:20	CDR	Private Medical Conference with Physical Exercise Specialists (S-band)
09:20-09:40	CDR	Work Prep
09:30-09:40	FE-4	MAI-75. Hardware Activation and Checkout
09:40-09:55	FE-4	KHROMATOMASS. Closeout Ops
09:45-11:15	FE-6	Physical Exercise (ARED)
09:50-10:00	FE-2	Private Medical Conference with Physical Exercise Specialists (S-band)
09:50-10:40	CDR	Replacing filters in FGB ΠC1, ΠC2 Dust Collectors (ΦΓΕ1ΠΓΟ_2_219_1, bag 410-32 (00054260R)). Update the IMS
10:00-10:10	FE-4	Private Medical Conference with Physical Exercise Specialists (S-band)
10:00-11:30	FE-2	БД-2 Exercise - Day 4
10:00-10:10	FE-3, FE-5	ATV Transfer Tagup
10:15-10:30	FE-5	Private Medical Conference
10:20-10:50	FE-4	LCS. Copying Data from RSE-LCS Laptop to RSS2 and Data Downlink
10:30-12:35	FE-5	EVA Tool Config
10:30-12:45	FE-3	EVA Tool Config
10:40-11:20	CDR	СОЖ Maintenance
11:05-11:15	FE-4	MAI-75. Hardware Activation and Checkout
11:15-12:15	FE-6	WRS Sample Collection
11:15-12:40	FE-4	Physical Exercise (ARED)
11:30-13:00	CDR	БД-2 Exercise - Day 1
11:30-13:00	FE-2	Configuring ΠxO and DC1 to Initial State after EVA
12:15-12:25	FE-6	WRS Water Sample Analysis
12:25-12:40	FE-6	IMAK Unpack
12:35-13:35	FE-5	LUNCH
12:40-12:50	FE-4	MAI-75. Hardware Activation and Checkout
12:40-13:40	FE-6	LUNCH
12:45-13:45	FE-3	LUNCH
12:50-12:55	FE-4	MAI-75. Equipment deactivation and cleanup
13:00-14:00	CDR, FE-2, FE-4	LUNCH
13:35-14:55	FE-5	ATV Cargo Operations
13:45-14:00	FE-3	VTR bypass cable config
13:55-15:05	FE-6	WMK In-Flight Water Processing
14:00-14:20	FE-4	IMS Delta File Prep
14:00-14:50	CDR	OBSTANOVKA. Measuring Resistance on ΠΒΚ Power Supply Circuits. Tagup with specialists (S-band)
14:00-17:15	FE-2	Configuring ΠxO and CO1 to Initial State after EVA
14:00-14:35	FE-3	Thermal Control System (TCS) P1 Thermal Radiator Rotary Joint (TRRJ) Imagery
14:50-15:40	CDR	Health Check of BΠ2 fan. <i>Tagup with specialists (S-band)</i>

14:55-15:05	FE-5	ATV Transfer Tagup
15:05-15:15	FE-5	Battery Stowage Assembly (BSA) Battery Recharge Terminate
15:05-15:35	FE-4	KULONOVSKYI KRISTALL. Hardware Setup and Configuration
15:05-18:30	FE-6	MSPR - 1553B Cable Swap
15:10-15:25	FE-3	Private Medical Conference
15:15-16:45	FE-5	Physical Exercise (ARED)
15:35-15:40	FE-4	MRM2 Comm Config
15:35-15:45	FE-3	SAMS Power On
15:40-15:50	CDR	ON MCC GO Mate BΠ2 fan telemetry connectors. <i>Tagup with specialists (S-band)</i>
15:40-16:40	FE-4	KULONOVSKYI KRISTALL Experiment Ops
15:45-16:45	FE-3	CEVIS Exercise
15:50-16:00	CDR	ON MCC GO OBSTANOVKA. Mating Connector and Closeout Ops. <i>Tagup with specialists (S-band)</i>
16:00-16:10	CDR	Health Check of BΠ2 fan (Closeout Ops). <i>Tagup with specialists (S-band)</i>
16:10-16:30	CDR	KULONOVSKYI KRISTALL Photography of the Experiment Ops
16:30-16:45	CDR	Private Medical Conference (Ku + S-band)
16:40-16:45	FE-4	MRM2 Comm Reconfig for Nominal Ops
16:45-17:10	FE-4	KULONOVSKYI KRISTALL Copy and Downlink Data via РСПИ
16:45-17:45	CDR	VELO Exercise - Day 1
16:45-17:45	FE-5	CEVIS Exercise
16:45-18:15	FE-3	ARED Exercise
17:10-17:25	FE-4	Private Medical Conference (Ku + S-band)
17:15-17:30	FE-2	Evening Work Prep
17:25-18:25	FE-4	БД-2 Exercise - Day 4
17:30-17:45	FE-2	Private Medical Conference (Ku + S-band)
17:45-18:25	CDR	Transfer of EU-TRITEL from Columbus to RS, Photography and IMS Ops
17:45-17:55	FE-5	EU-TRITEL P/L Handover to RS
17:45-17:55	FE-2	Photo of EU-TRITEL P/L Handover to RS
17:55-18:55	FE-2	VELO Exercise - Day 4
17:55-18:15	FE-5	Evening Work Prep
18:15-18:25	FE-3, FE-5	Installation of REBA batteries
18:25-18:45	FE-3, FE-5	REBA Powered Equipment Test
18:25-18:55	CDR, FE-4	Evening Work Prep
18:30-18:40	FE-6	TOCA 2 Data Recording
18:40-18:55	FE-6	Evening Work Prep
18:45-18:55	FE-3, FE-5	Evening Work Prep
18:55-19:20	-	Daily Planning Conference (S-band)
19:20-19:30	-	Evening Work Prep

19:30-21:30	-	Pre-sleep
21:30-06:00	-	SLEEP
Task List	CDR, FE-2, FE-4	ECON-M. Observations and Photography
		URAGAN. Observations and Photography
		Report Preparation for Roskosmos site

Notes:

- 1. SM Window No. 9 shutter opening is at crew discretion w/ Report to MCC
- 2. See OSTPV for references to US activities.
- 3. Pre-sleep ops: daily food prep, dinner, pre-sleep
- 4. Russian crew uses US exercise equipment strictly per F24 or OSTPV
- 5. Do not use ISS RS windows during the LCS experiment at 07:50-08:05, 09:25-09:40, 12:40 12:55

End of Radiogram