## MEDICAL MONITORING. ATV FUEL AND OXIDIZER REFILLING SYSTEMS [3y $\Gamma$ , 3yO] LEAK CHECKS (START).

(START).	CREW	ACTIVITY
06:00-06:05	FE-6	BISP Pill Ingestion
06:00-06:05	CDR	Elektron-VM System Monitoring
06:00-06:10	FE-5	Morning Inspection
06:05-06:10	FE-6	
06:05-06:15	CDR	Calf Volume Measurement
06:10-06:30	FE-5	D. A. I. C.
06:10-06:40	FE-6	Post-sleep
06:15-06:25	CDR	MO-8. Setup
06:25-06:35	CDR	Morning Inspection.  Inspection of CM-Y connector on MHP-HC pump behind ACY panel 139.
06:30-06:35	FE-5	Body Mass Measurement
06:35-07:00	CDR	Doct cloop
06:35-06:45	FE-5	Post-sleep
06:40-06:55	FE-6	DDE ALCA OT
06:45-07:35	FE-5	BREAKFAST
06:55-07:00	FE-6	Body Mass Measurement
07:00-07:40	FE-6	BREAKFAST
07:00-07:05	CDR	Body Mass Measurement
07:05-07:15	CDR	MO-8. Cleanup
07:15-07:50	CDR	BREAKFAST
07:35-07:50	FE-5	Work Prep
07:40-07:50	FE-6	Work Flep
07:50-08:05		Daily Planning Conference (S-band)
08:05-08:20	FE-5	Work Prep
08:05-08:15	FE-6	work Fiep
08:05-08:25	CDR	BREAKFAST
08:15-08:35	FE-6	MELFI 1 Ice Brick Insert 1
08:20-08:40	FE-5	QDMA Swap
08:25-08:50	CDR	Work Prep
08:40-12:10	FE-5	PBA and PFE Audit
08:50-09:00	CDR	ГФИ-1 [Geophysical Studies]. Start SONY DCR-TRV900E Camcorder Battery Charge
08:50-09:00	FE-6	EHS GC/DMS Ops Start
09:00-09:40	CDR	Auxiliary Laptop Anti-Virus Update
09:00-09:30	FE-6	DECLIC ALICE-Like Insert Installation
09:30-09:35	FE-6	MSG Checkout MLC Power On
09:40-10:10	CDR	Tool search and equipment prep prior to airduct R&R
09:40-09:45	FE-6	MSG Sensor Checkout Step 1
09:45-10:45	FE-6	Physical Exercise T 2
10:30-12:00	CDR	Physical Fitness Evaluation (on treadmill)

10:45-12:15	FE-6	Physical Exercise (ARED)
12:00-13:00	CDR	Physical Exercise (VELO), Day 4
12:10-12:30	FE-5	MELFI 3 Ice Brick Insert 1
12:15-12:25	FE-6	WRS Water Sample Analysis
12:55-13:00	FE-6	Configure WHC for internal ЕДВ-У use
13:00-13:30		E26/27-E27/28 Crew Conference
13:30-14:30		LUNCH
14:30-15:00	CDR	СОЖ Maintenance
14:30-15:20	FE-5,FE-6	HTV Undock Onboard Training
15:00-15:30	CDR	Counter Measure System (CMS) Harmful Contaminant Measurements in SM
15:20-15:30	FE-5,FE-6	HTV Timeline Conference
15:30-15:40	CDR	PAO Hardware Setup
15:30-16:00	FE-5	BXF Experiment Hardware Gather
15:30-15:35	FE-6	EHS GC/DMS Ops Terminate
15:35-15:40	FE-6	MSG Sensor Checkout Step 2A
15:40-15:50	FE-6	TOCA Sample Data Recording and Transfer
15:40-15:50	CDR	Crew Prep For PAO
15:50-16:10	CDR	TV Greeting to the UN General Assembly (Ku+S-band) TV Greeting to the people and guests of the Saratov region (Ku+S-band)
15:55-16:10	FE-6	Connect CWC to WPA Waste Water Tank
16:00-17:00	FE-5	Physical Exercise (CEVIS)
16:10-16:20	FE-6	MSG Sensor Checkout, Step 3A
16:20-17:10	FE-6	Pack and stow items on HTV2
16:25-17:35	CDR	RELAXATION Hardware Installation on Window #9. Tagup with specialists (S-band)
17:00-17:15	FE-5	ARED Flywheel Cylinder Evacuation
17:10-17:20	FE-6	HTV2 Cargo Transfer Conference
17:15-18:45	FE-5	Physical Exercise (ARED)
17:20-17:30		Restore CWC and WPA original configuration
17:35-18:25	CDR	RELAXATION Activation, Mode Selection, and Observation. <i>Tagup with specialists (S-band)</i>
17:55-18:55	FE-6	MSG Inspection And Cleaning
18:25-18:40	CDR	RELAXATION Closeout Ops. Tagup w/ specialists (S-band)
18:40-19:00	CDR	Evening Work Prep
18:45-19:05	FE-5	Evening Work Prep
18:55-19:05	FE-6	VHF test using US ground sites
19:00-19:05	CDR	Elektron-VM System Monitoring
19:05-19:20		Daily Planning Conference (S-band)
19:20-19:30		Evening Work Prep
19:30-19:35	FE-6	MPC Power Up
19:30-21:30	CDR,FE-5	Pre-sleep
19:35-21:25	FE-6	
21:25-21:30	FE-6	MPC Power Down
21:30-06:00		SLEEP
	1	H .

Task list	CDR	IMS Update

## Notes:

- SM Window #9 shutter opening is at crew discretion w/ Report to MCC
   See OSTP for references to US activities
- 3. Pre-sleep ops: daily food prep, dinner, pre-sleep End of Radiogram