Rg 6348u Form 24 for 06/01/2011
Unit PT-50 (EPS) R&R. ВД-СУ mode ON/OF and БИТС (Onboard telemetry system) powerup/powerdown

| GMT | Crew | ACTIVITY |
|-------------|----------|---|
| 06:00-06:10 | CDR | Morning inspection |
| 06:00-06:10 | FE-1 | Morning inspection. <i>Monitoring circuit breaker (A3C) on Power Switching Panel (БВП) in DC1 and fuses in fuse boxes БПП-30, 36 in DC1</i> |
| 06:00-06:05 | FE-3 | Self-inspection for reaction |
| 06:05-06:10 | FE-3 | Morning inspection |
| 06:10-06:40 | | Post-sleep |
| 06:40-07:30 | | Breakfast |
| 07:30-07:45 | | Daily planning conference (S-band) |
| 07:45-08:10 | FE-3 | Morning work prep |
| 07:45-08:15 | CDR,FE-1 | Morning work prep |
| 08:10-08:25 | FE-3 | EHS - starting GC/DMS |
| 08:15-10:45 | CDR | Rastenia-2. HW setup, SW update and testing |
| 08:15-08:25 | FE-1 | FMK monitors deploy |
| 08:25-10:20 | FE-3 | Post-Shuttle housekeeping |
| 09:30-09:50 | FE-1 | Sampling with GSC |
| 09:50-10:30 | FE-1 | СОЖ (ECLSS) Maintenance |
| 10:20-10:30 | FE-3 | Initial noise measurement in crew cabin |
| 10:30-11:45 | FE-3 | CQ – removing a support |
| 10:30-12:00 | FE-1 | PE ARED |
| 10:45-11:45 | CDR | Rastenia-2 (ЛАДА). Filling water container. Tagup with specialist (S-band) |
| 11:45-11:55 | FE-3 | FIR – prepping for video |
| 11:55-12:10 | FE-3 | FIR – opening rack doors |
| 11:55-12:55 | CDR | РЕ ВЕЛО - 3 |
| 12:00-13:00 | FE-1 | PE T2 - 3 |
| 12:10-12:15 | FE-3 | LMM – rotating microscope |
| 12:15-12:35 | FE-3 | Changing biosamples |
| 12:35-12:45 | FE-3 | LMM – Rotating into operational config |
| 12:45-13:00 | FE-3 | FIR – closing rack doors |
| 13:00-14:00 | | Midday meal |
| 14:00-14:10 | CDR,FE-3 | Prepping US HW for a TV-session via Ku+S-band |
| 14:10-14:15 | FE-3 | EHS – finishing sampling |
| 14:15-14:35 | FE-3 | DECLIC - RHDD replace |
| 14:25-15:15 | FE-1 | Prepping for R&R – unit PT-50-1M #3 (A203) – and demating connectors X4/100 (in eclipse), X5/100, X6/100, X2/100, X3/100 |
| 14:35-14:40 | FE-3 | Rebooting SLT laptops |
| 14:40-14:55 | FE-3 | PMC |
| 14:45-15:45 | CDR | Updating БРИ-server config file to version 4.2.4 and ACΠ-M config file for version 1.2 |
| 14:55-15:10 | FE-3 | Final noise measurement in crew cabin |
| 15:15-15:25 | FE-1 | On MCC Go Demating ТМИ-connectors PT-50 X101/42, X1326/42 (41) from БИТС2-12 |
| 15:15-16:15 | FE-3 | PE CEVIS |
| | | |

| 15:25-17:05 | FE-1 | R&R – replacing unit PT-50-1M #3 with new unit #93040034 from SM spares |
|-------------|----------|---|
| 15:45-16:05 | CDR | Video transmission test |
| 16:05-17:35 | CDR | PE T2 - 3 |
| 16:15-17:45 | FE-3 | PE ARED |
| 17:05-17:15 | FE-1 | On MCC Go Mating ТМИ-connectors PT-50 X1326/42 (41), X101/42 to БИТС2-12 |
| 17:15-17:45 | FE-1 | Inspecting and photographing windows in RS (preparation) |
| 17:45-17:55 | CDR,FE-1 | Crew prepares for PAO |
| 17:45-18:00 | FE-3 | PPC |
| 17:55-18:15 | CDR,FE-1 | TV-greetings (Ku+S-band) |
| 18:00-18:20 | FE-3 | Comm check |
| 18:15-18:35 | CDR | Pre-sleep ops |
| 18:15-18:45 | FE-1 | Mating connectors X3/100, X2/100, X6/100, X5/100, X4/100 (in eclipse) and final steps |
| 18:30-18:35 | FE-3 | Pre-sleep ops |
| 18:35-18:55 | CDR | IMS edit |
| 18:45-18:55 | FE-1 | Monitoring absence of cooling agent in half-coupling 4ΓБ4 KOБ2 housing |
| 18:55-19:10 | | DPC (S-band) |
| 19:10-19:20 | FE-1 | Evening work prep |
| 19:10-19:30 | FE-3 | Evening work prep |
| 19:20-21:15 | FE-1 | Pre-sleep ops |
| 19:30-21:30 | CDR | Pre-sleep ops |
| 19:30-19:35 | FE-3 | MPC – powering up |
| 19:35-21:20 | FE-3 | Pre-sleep ops |
| 21:15-21:30 | FE-1 | БАР PIREN charging start |
| 21:20-21:25 | FE-3 | Self-inspection for reaction |
| 21:25-21:30 | FE-3 | MPC powerdown |
| 21:30-06:00 | | Sleep |
| Task list | CDR,FE-1 | Preparing reports for Roscosmos website |

- Notes:
 1. SM Window #9 shutter opening is at crew discretion w/ Report to MCC
 2. See OSTP for references to US activities
 3. Pre-sleep ops: daily food prep, dinner, pre-sleep

End of r/g