Form 24 for 08/20/08

PREPARATIONS FOR ZVENO-B HARDWARE INSTALLATION. INSTALLATION OF RELAXATION HARDWARE

GMT	CREW	ACTIVITY
06:00-06:10		Morning Inspection
06:10-06:20	FE-1 FE-2	Post-sleep
06:10-06:30		
06:10-06:20	CDR	Hematocrit test
06:20-06:50		Post-sleep
06:20-06:30	FE-1 FE-2	Hematocrit test
06:30-06:40		
06:30-06:50	FE-1	Deat class
06:40-06:50	FE-2	Post-sleep
06:50-07:40		BREAKFAST
07:40-07:55		Daily Planning Conference (S-band)
07:55-08:25	CDR, FE-2	Prep for Work
07:55-08:00	FE-1	Hematocrit, Equipment stow
08:00-08:25		Prep for Work
08:25-08:55	CDR	Manual Pressure Gauge Reading Cross Checks
08:25-09:15	FE-1	Pille dosimeter reading
08:25-09:55	FE-2	Physical Exercise (RED)
08:55-09:00	CDR	Laptop RS2 activation
09:00-09:30		Setting up SM Central Post Remote Work Station in the USOS. Remote Work Station Tests
09:15-09:30	FE-1	LULIN. Set up dosimeters to charge
09:30-09:35	CDR	Laptop RS2 Shutdown
09:30-11:30	FE-1	Preparing to install Zveno-B hardware and cables. Tagup with specialists as necessary (S-band)
09:35-10:30	CDR	Physical Exercise (VELO+RED)
09:55-10:55	FE-2	Physical Exercise (CEVIS)
10:30-11:30	CDR	Preparing to install Zveno-B hardware and cables. Tagup with specialists as necessary (S-band)
10:55-11:25	FE-2	KU-band transmitter relocation and testing
11:25-12:10		CGBA-4 Payload Transfer
11:30-11:45	FE-1	Verify ИП-1 Flow Meter Positions
11:35-13:05	CDR	RELAXATION. Equipment setup. Tagup with specialists (S-band) /
11:45-11:55	FE-1	PLANTS-2. Photography
12:10-12:55	FE-2	CGBA-5 Payload Transfer
12:55-13:55		ATV Transfers
13:00-13:55	FE-1	SM ΠΦ1-4 dust filter cartridge replacement(<i>ΦΓБ</i> 1 <i>ΠΓO</i> _2_226_1, bag 352-2, b/c 00037761R)
13:05-13:20	CDR	RELAXATION. Setting parameters and starting the hardware. Tagup with

		specialists (S-band)
13:20-13:35		RELAXATION. Earth observation and vide Tagup with specialists (S-band)
13:35-13:55		RELAXATION. Hardware teardown
13:55-14:55		LUNCH
14:55-16:10	FE-2	ATV cargo transfers to Columbus
14:55-15:35	FE-1	СОЖ Maintenance
14:55-16:55	CDR	Т97 БР9-ЦУ-8 Parameter Verification. Tagup with specialists (S-band)
15:35-15:55	FE-1	IMS Update
15:55-16:25		Evening Work Prep
16:10-16:40	FE-2	JAXA Ground Strap Retrieval
16:25-18:55	FE-1	MBI-8. Countermeasures on TVIS
16:40-17:25	FE-2	USOS Ground Strap Retrieval
16:55-18:25	CDR	Physical Exercise (CEVIS)
17:25-18:25	FE-2	OUM-PFE – Hardware Installation
18:25-19:00	CDR, FE-2	Evening Work Prep
18:55-19:00	FE-1	Transfer of TVIS, RED, and HRM data to MEC
19:00-19:15		Daily Planning Conference (S-band)
19:15-19:30		Evening Work Prep
19:30-20:00		DINNER
20:00-20:30	CDR, FE-1	Daily Food Prep
20:00-20:20	FE-2	
20:20-20:35		Private Family Conference (Ku + S-band)
20:30-21:30	CDR, FE-1	Pre-sleep
20:35-21:25	FE-2	
21:25-21:30		Log entry reminder
21:30-06:00		SLEEP
Task List	FE-1	PLANTS-2. Payload Status Check

Notes:

- SM Window #9 shutter opening is at crew discretion with Report to MCC
 See OSTP for references to US activities.
- 3. Access to OCA is unavailable between 10:00 11:45

End of Radiogram