Disabling/Enabling ВД-СУ Mode • SM Internal Thermal Loop 2 (КОБ2): Pump Panel R&R

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30].	BREAKFAST
07:30-08:00		Prep for work
08:00-08:15		Daily planning conference (S-band)
08:15-08:55	CDR	INTERACTIONS: data collection and backup
08:15-08:45	- FE-1	MSG payload review (science program prepared for Spanish astronaut)
08:45-10:00		Physical exercise (TVIS)
08:55-09:00	CDR	БРПК separator inspection
09:00-10:00		Physical exercise (VELO + Load Trainer – 1 / day 2)
10:00-11:00	FE-1	PSC HD ghost recovery
10:20-11:50	CDR	SM Internal Thermal Loop 2 (ΚΟΕ2): pump panel 4CΠH2 R&R. <i>Tagup</i> with ground specialists. (S-band)
11:00-12:00	FE-1	Node 1 smoke detector 2: cleaning
11:50-12:00	CDR	On MCC Go: demating TLM connectors from БИТС2-12 (S-band)
12:00-13:00		LUNCH
13:00-16:00	FE-1	Printing out new pages for Emergency ODF
13:00-14:30	CDR	SM Internal Thermal Loop 2 (KOE2): pump panel 4CПH2 R&R. Photo survey of the installation site. <i>Tagup with ground specialists.</i> (S-band)
14:30-14:40		On MCC Go: mating TLM connectors to БИТС2-12 (S-band)
14:40-16:10		SM Internal Thermal Loop 2 (ΚΟБ2): pump panel 4CΠH2 R&R. <i>Tagup</i> with ground specialists (S-band)
16:00-16:15	FE-1	Inserting new pages into Emergency ODF book
16:10-17:40	CDR	Physical exercise (TVIS-2)
16:15-17:30	FE-1	Physical exercise (RED)
17:30-17:50		IMS file prep
17:40-18:15	CDR	СОЖ maintenance
17:50-18:00	FE-1	Download of TVIS/RED files to MEC
18:00-18:30		Daily plan review
18:15-18:30	CDR	Private medical conference (KU+S-band)
18:30-18:45	FE-1	Trivate medical comercine (NO+3-band)
18:30-18:45	CDR	Daily plan review
18:45-19:00		Daily planning conference (S-band)
19:00-19:30		Prep for work
19:30-20:00		DINNER
20:00-20:30].	Daily food prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP

Note: See OSTP for references to US activities

End of radiogram