Form 24 for 06/30/.2011

| GMT | CREW | ACTIVITY |
|-------------|--|---|
| 06:00-06:10 | CDR, FE-1, FE-3, FE-5, FE-6 | Morning Inspection |
| 06:00-06:05 | FE-4 | PLASMA CRYSTAL. Pressure check |
| 06:05-06:10 | FE-4 | Morning Inspection |
| 06:10-06:40 | | Post-sleep |
| 06:40-07:30 | | Breakfast |
| 07:30-07:50 | | Prep for Work |
| 07:50-08:00 | CDR | MOLNIYA-GAMMA. Downlink of Science and Service Data from Payload Server (БСПН) via RSS1 (start) |
| 07:50-07:55 | FE-1 | Fill SM Rodnik from Progress 411 Rodnik 5B2 – Closeout Ops |
| 07:55-08:05 | | BRI Log Dump |
| 08:05-08:30 | | Daily Planning Conference (S-band) |
| 08:30-08:55 | FE-3 | On-Orbit Hearing Assessment (OOHA) with EarQ Software Test |
| 08:30-09:30 | FE-6 | Physical Exercise T2 |
| 08:30-10:00 | CDR | Physical Exercise ARED |
| 08:30-08:40 | | Glovebox (MSG) - Activation |
| 08:40-08:50 | FE-5 | SHERE Experiment - Historical Documentation Video/Photos |
| 09:00-11:30 | | SHERE Experiment – Hardware Setup |
| 09:00-09:30 | FE-3 | Node 2 CCAA Heat Exchanger (HX) ORU Preparation |
| 09:05-09:10 | | CTTC configuration for MRM2 for PL |
| 09:10-09:30 | FE-4 | PLASMA CRYSTAL. Activate Hardware and Start the Experiment |
| 09:10-09:35 | FE-1 | On-Orbit Hearing Assessment (OOHA) with EarQ Software Test |
| 09:30-09:45 | FE-6 | Remove Node 2 CCAA Heat Exchanger (HX) Flight Support Equipment (FSE) |
| 09:35-10:05 | FE-4 | TV ISS-MCC.PLASMA CRYSTAL. Start and Monitor the Experiment |
| 09:40-09:45 | FE-1 | PLASMA CRYSTAL-3 PLUS. Check TV Signal on BKY Monitor and on SSC2 Laptop |
| 09:45-10:55 | FE-3, FE-6 | Remove Node 2 CCAA Heat Exchanger (HX) |
| 10:00-11:00 | FE-1 | PHYSICAL EXERCISE ARED |
| 10:05-11:05 | FE-4 | PHYSICAL EXERCISE T2-1 |
| 10:30-10:55 | | On-Orbit Hearing Assessment (OOHA) with EarQ Software Test |
| 10:55-11:00 | CDR | Crew Preparation for PAO Event |
| 10:55-11:25 | FE-3 | Node 2 CCAA Sample |
| 10:55-11:25 | FE-6 | Node 2 CCAA Heat Exchanger (HX) Line Transfer |
| 11:00-12:00 | CDR | RELAXATION. Install Hardware. Tagup with specialists (S-band) |
| 11:05-11:10 | | Crew Preparation for PAO Event |
| 11:10-11:30 | FE-4 | PLASMA CRYSTAL. Terminate the Experiment |
| 11:10-12:40 | FE-1 | FGB Internal Thermal Loop 1-2 Final Hydraulic Connector |
| 11:25-13:00 | FE-3, FE-6 | Install Node 2 CCAA HX ORU |
| 11:30-12:25 | FE-4 | PLASMA CRYSTAL. Deactivate Hardware |
| 11:30-13:00 | FE-5 | PHYSICAL EXERCISE ARED |

| 12:00-12:55 | CDR | RELAXATION. Activate, Select Modes, Perform Observations |
|-------------|--------------------|--|
| 12:25-12:55 | FE-4 | PLASMA CRYSTAL. Remove Hardware |
| 12:40-12:55 | FE-1 | Equipment Setup and Crew Preparation for TV PAO To=12:37 , T1 , T2 , T3 from CΠΠ |
| 12:55-13:05 | CDR, FE-1, FE-4 | TV ISS-MCC TV PAO with Winner and Participants of Star Relay Competition |
| 13:00-14:00 | FE-3,FE-5,FE- 6 | LUNCH |
| 13:05-13:10 | FE-4 | Comm Reconfiguration in MRM2 |
| 13:05-14:00 | CDR, FE-1 | LUNCH |
| 13:10-14:00 | FE-4 | LUNCH |
| 14:00-14:30 | | ULF7 Crew Conference |
| 14:30-15:00 | FE-3 | Audit M-02 bag containing water sampling equipment - start |
| 14:30-17:30 | FE-1, FE-4 | CTTC functional check. Tagup with specialists (S-band) Audit |
| 14:30-15:10 | CDR | RELAXATION. Copy Data and Remove Hardware. <i>Tagup with specialists</i> (S-band) |
| 14:30-14:40 | FE-6 | Food Questionnaire |
| 14:30-14:40 | | RWS Checkout |
| 14:40-14:45 | FE-5 | RWS Cable Checkout |
| 14:45-14:55 | | RWS Checkout |
| 14:55-15:00 | | (RWS) Cupola Crew Restraint (CCR) Installation |
| 15:00-15:45 | FE-5, FE-6 | SSRMS Ops |
| 15:05-16:05 | FE-3 | Physical Exercise CEVIS |
| 15:10-15:20 | CDR | MOLNIYA-GAMMA Downlink of Science and Service Data from Payload Server (БСПН) via RSS1 (terminate) |
| 15:20-16:20 | | Physical Exercise T2-4 |
| 15:45-17:15 | FE-6 | Node 2 CCAA Closeout Ops |
| 15:45-15:50 | | ISSAC Laptop Power On Only |
| 15:50-16:10 | FE-5 | Shear History Extension Rheology Experiment (SHERE) Experiment Hardware Power On |
| 16:05-17:35 | FE-3 | Physical Exercise ARED |
| 16:10-16:25 | FE-5 | SHERE – Load SW |
| 16:20-17:00 | CDR | СОЖ Maintenance |
| 16:25-16:40 | | SHERE Experiment – Power Off |
| 16:40-16:45 | FE-5 | Glovebox (MSG) – Power off |
| 16:45-17:45 | | Physical Exercise CEVIS |
| 17:30-19:00 | FE-1 | Physical Exercise T2-4 |
| 17:30-17:40 | FE-4 | CTTC Comm Assets Switchover to Backup Set |
| 17:35-19:05 | FE-6 | Physical Exercise ARED |
| 17:40-18:40 | FE-4 | Physical Exercise BEЛО-1 |
| 17:45-18:15 | FE-3 | Audit M-02 bag containing water sampling equipment - Terminate |
| 17:50-18:05 | | Verify ИП-1sensor positions |
| 18:05-18:25 | - CDR | IMS Update |
| 18:15-19:00 | FE-3, FE-5 | SSRMS Maneuver |
| 18:40-19:05 | FE-4 | Evening Work Prep |

| 18:45-19:05 | CDR | Evening Work Prep |
|-------------|------------------------------|---|
| 19:00-19:05 | FE-5 | RWS Cable Checkout |
| 19:00-19:05 | FE-1 | Evening Work Prep |
| 19:00-19:05 | FE-3 | RWS Cupola Crew Restraint (CCR) Removal |
| 19:05-19:30 | | Daily Planning Conference (S-band) |
| 19:30-19:45 | | Pre-sleep |
| 19:45-20:05 | | Crew Conference with Astronaut Office Management (S-band) |
| 20:05-21:30 | CDR, FE-4, FE-5, FE-6 | Pre-sleep |
| 20:05-21:20 | FE-1 | Pre-sleep |
| 20:05-20:10 | FF 2 | MPC Power on |
| 20:10-21:25 | FE-3 | Pre-sleep |
| 21:20-21:30 | FE-1 | RUSALKA. Battery Charge |
| 21:25-21:30 | FE-3 | MPC- Power off |
| 21:30-06:00 | | SLEEP |
| TASK LIST | CDR, FE-1, FE-4 | Reportage Preparation for Roskosmos |

Note:

- 1. Window #9 shutter opening at crew's discretion and w/Report to MCC
- 2. See OSTP for references to US activities
- 3. Pre-sleep ops: daily food prep, dinner, pre-sleep
- 4. FE-4 tagup w/ specialists during PLASMA CRYSTAL ops (S-band+YKB)

End of Radiogram