Progress M-10 No. 247 Docking to SM Aft

GMT	CREW	ACTIVITY
06:00-06:10		Morning inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:55	FE-1	Work prep
07:30-08:00	CDR, FE-2	Work prep
07:55-08:00	FE-1	PLANTS-2. Equipment monitoring
08:20-08:35		Daily planning conference (S-band)
08:35-08:45	FE-2	EVARM – reader activation
08:35-08:45	CDR	Setup for microbiology analysis
08:45-10:15	CDR	Surface sampling, analysis (T+5)
08:45-08:55	FE-2	Microbiological analysis of water: photo-imaging
08:55-09:00	FE-2	CO2 level reading using carbon dioxide monitor
09:00-09:15	FE-2	EVARM – reading
09:15-09:35	FE-2	EVARM – data transfer, equipment stow
09:25-10:55	FE-1	Physical exercise (TVIS, day 4)
09:35-09:45	FE-2	HRF: power-up
09:45-09:55	FE-2	Water microbial analysis: photo-imagery
09:55-10:25	FE-2	Scheduled CSA-CP maintenance
10:15-10:35	CDR	Microbial samples: data download to MEC
10:25-10:55	FE-2	30 minutes to review Glove Box experiment procedure
10:35-10:45	CDR	Microbiology samples: data download to MEC
10:50-11:50	CDR	Physical exercise (TVIS)
10:55-11:05	FE-2	HRF: power-down
11:00-11:40	FE-1	СОЖ maintenance
11:05-12:00	FE-2	Physical exercise (CEVIS)
11:50-11:55	CDR	Weekly TVIS maintenance
11:55-12:55	CDR, FE-1	LUNCH
12:00-12:55	FE-2	LUNCH

12:55-13:00	FE-2	Scheduled CSA-CP maintenance
13:00-13:30		Progress M-10 No. 247 Docking Prep
13:30-14:50	CDR, FE-1	Progress M-10 No. 247 Docking to SM Aft
13:30-15:00	FE-2	Progress M-10 No. 247 Docking to SM Ait
14:50-15:00	CDR, FE-1	Ku-band TV Deactivation following Soyuz/Progress docking/undocking
15:00-16:00	FE-1	Physical exercise (VELO + Load Trainer 1, day 4)
15:00-15:40	FE-2	IMS File Prep
15:10-16:30	CDR	Physical exercise (RED)
15:40-15:55	FE-2	Private medical conference (S-band)
15:55-16:00	FE-2	CO2 level reading using Carbon Dioxide Monitor
16:00-16:15	FE-1	Private medical conference (S-band)
16:20-17:50	FE-2	Physical exercise (RED)
16:30-16:45	CDR	Private medical conference (S-band)
16:50-17:50	CDR, FE-1	ПрК-Progress interface leak check
18:00-19:00		Memorial service
19:00-19:15	FE-2	Work prep
19:00-19:20	CDR, FE-1	СУ-ПрК and Progress-СУ hatch opening
19:20-19:40	CDR, FE-1	Quick-release threaded clamp installation
19:40-19:55		Daily planning conference (S-band)
19:55-20:20		DINNER
20:20-20:35	FE-1	AK-1M air sampling
20:20-20:40	CDR, FE-2	Daily food prep
20:35-20:40	FE-1	Progress deactivation
20:40-21:30		Pre-sleep
21:30-06:00		SLEEP

Note: See OSTP for references to US activities. End of radiogram