INSTALLATION OF СБИ [ONBOARD MEASUREMENT SYSTEM] VSPLESK P/L CONTROL CABLES

GMT	CREW	ACTIVITY
06:00-06:10		Morning Inspection
06:10-06:40		Post-sleep
06:40-07:30	<u> </u>	BREAKFAST
07:30-08:00		Prep for Work
08:00-08:15		Daily Planning Conference (S-band)
08:15-10:15	FE-2	Biolab Incubator Rotor Locking Actuator Exchange Rotor B
08:15-08:45	FE-1	Elektron Purge And Power Down
08:45-11:45		Installation of [СБИ] VSPLESK P/L Control Cables (seven). <i>Tagup with specialists (S-band)</i>
08:45-09:15	CDR	Health Maintenance System (HMS) Defibrillator Checkout
09:15-09:25		Copy Data From Payload Server [БСПН] Using RSS1
09:25-10:25		Physical Exercise (CEVIS + RED)
10:15-11:45	FE-2	Physical Exercise (RED)
10:25-10:35		Copy Data From Payload Server [БСПН] Using RSS1
10:35-11:15	CDR	СОЖ Maintenance
11:15-11:45		Counter Measure System (CMS) Harmful Contaminant Measurements in SM
11:45-12:45	FE-2	Inspection of Portable Breathing Apparatus (PBA) and Portable Fire Extinguisher (PFE)
11:45-12:15	CDR,FE-1	Connecting СБИ [Onboard Measurement System] VSPLESK P/L Control Cables (seven). <i>Tagup with specialists (S-band)</i>
12:15-12:30		On MCC Go Mate VSPLESK Telemetry Connectors to БИТС2-12 (S-band)
12:30-12:40		Connecting СБИ (Onboard Measurement System) VSPLESK Control Cables (seven) – closeout ops. <i>Tagup with specialists (S-band)</i>
12:45-13:45		LUNCH
13:45-14:00	CDR	Private Medical Conference (Ku + S-band)
13:45-13:55	EE 2	EDR. Rack Deactivation
13:55-14:05	FE-2	ANITA Troubleshooting
14:00-14:15	FE-1	Private Medical Conference (Ku + S-band)
14:15-15:15		1J Timeline Review (S-band)
15:15-15:45		1J Timeline Conference (S-band)
15:45-17:15	FE-1	Physical Exercise (TVIS), day 2
15:45-16:15	CDR	AOK ΓΑΗΚ-4M Data Readout
15:45-16:45	FE-2	Physical Exercise (CEVIS)
16:15-16:35	CDR	IMS Update
16:35-17:10	CDK	Prep for Work
16:45-17:30	FE-2	Common Berthing Mechanism (CBM) On Board Training (OBT)
17:10-18:40	CDR	Physical Exercise (TVIS), day 2
17:15-18:15	FE-1	Physical Exercise (CEVIS + RED)
17:30-17:45	FE-2	Private Medical Conference (Ku + S-band)

17:45-18:45		Crew Departure Prep
18:15-18:45	FE-1	Prep for Work
18:40-18:45	CDR	Transfer of TVIS, RED, and HRM data to MEC
19:05-19:20		Daily Planning Conference (S-band)
19:20-19:30		Prep for Work
19:30-20:00		DINNER
20:00-20:30		Daily Food Prep
20:30-21:20	FE-1	Pre-sleep
20:30-21:30	CDR,FE-2	
21:20-21:30	FE-1	SONOCARD. Experiment Start
21:30-06:00		SLEEP

- Notes:

 1. SM Window #9 shutter opening is at crew discretion with Report to MCC

 2. See OSTP for references to US activities.

 End of Radiogram