Radiogram No. 6486u Form 24 for 11/02/07 **(preliminary) Joint Flight with STS. USOS EVA5**

GMT	CREW	ACTIVITY
03:10-03:20	FE-2	Morning inspection. Inspection of Circuit Breaker [A3C]on DC1 Power Switch Panel [БВП] and fuses in DC1 Fuse Boxes БПП-30, БПП-36
03:10-03:15	CDR	Immune - Dry Saliva Sample Collection
03:10-03:45	FE-1	Post-sleep
03:10-03:15	FE-2-16	Immune - Dry Saliva Sample Collection
03:15-03:25	FE-2-16	Morning inspection
03:15-03:45	CDR	Post-sleep
03:20-03:50	FE-2	
03:25-03:55	FE-2-16	
03:45-04:55	FE-1, CDR	EVA - Break/Pre-breathe BREAKFAST
03:50-04:40	FE-2	BREAKFAST
03:55-04:45	FE-2-16	
04:40-05:10	FE-2	Prep for Work
04:45-05:15	FE-2-16	
05:05-06:25	CDR,FE-1	EVA Prep
05:10-05:15	FE-2	HAM Radio Powerdown in SM
05:15-06:00	FE-2	AmiA filter removal in LAB105
05:20-05:30	FE-2-16	Daily planning conference (VHF)
05:30-06:30	FE-2-16	Physical Exercise (TVIS)
06:00-06:30	FE-2	Removal of insert hose for AmiA filter ops
06:25-06:40	CDR,FE-1	EMU purge
06:30-08:00	FE-2, FE-2-16	Handover
06:40-07:30	FE-1, CDR	Pre-breathe in EMU
07:30-08:00	CDR, FE-1	Crew Lock Depress
08:00-08:05	CDR, FE-1	Post Depress and A/L Egress
08:00-08:45	FE-2	PHOSRA-1 coolant sampling
08:05-08:30	FE-1, CDR	Crew Lock Egress
08:05-14:35	FE-2-16	EVA IVA support
08:30-08:50	CDR, FE-1	Stow SSPTS cable
08:50-09:30	CDR	Stow PMA2/LAB Umbilical
08:50-09:50	FE-1	
09:30-10:15	CDR	Retrieve Lab CETA Light
09:35-10:35	FE-2	Physical Exercise (TVIS)
09:50-11:00	FE-1	Temp Stow STBD Tray Avionics
10:15-11:00	CDR	
10:35-11:35	FE-2	LUNCH
11:00-12:00	CDR	Base Band Signal Processor (BSP) Retrieval
11:00-12:00	FE-1	P1 NTA Bolt Release and Tool Prep

11:35-11:55	FE-2	IWIS data copy
11:55-12:10	FE-2	IWIS installation
12:00-12:50	CDR, FE-1	Remove and Stow Active Common Berthing Mechanism (ACBM) cover
12:10-12:40	FE-2	Disconnect QD12 to Isolate N2 Line to A/L Tanks
12:40-12:55	FE-2	Questionnaire - journal entry
12:50-13:30	CDR	Mate S0/N1 SM Power Cable
12:50-13:40	FE-1	Configure PMA1/FGB H Jumpers
12:55-13:55	FE-2	Physical Exercise (RED)
13:30-14:10	CDR	Tool Preparation for Ingress
13:40-14:10	FE-1	
13:55-14:00	FE-2	Transfer TVIS/RED/CEVIS/HRM data to MEC
14:00-14:05	FE-2	Preparation of DCS760 cameras for EVA glove inspection
14:05-14:45	FE-2	СОЖ maintenance
14:10-14:35	FE-1, CDR	Crew Lock ingress before repress
14:35-14:40	CDR,FE-1	Crew Lock Pre-Repress
14:40-14:50	FE-1,CDR	Crew Lock Repress
14:45-15:05	FE-2	IMS update
14:50-16:10	FE-1,CDR	Joint Airlock Ops Post-EVA
14:55-15:25	FE-2-16	Evening work prep
15:05-15:25	FE-2	
15:25-15:40	FE-2-16, FE-2	Daily Planning Conference (S-band)
15:40-16:10	FE-2, FE-2-16	Evening work prep
16:10-16:40	FE-2, FE-2-16	Daily Food Prep
16:10-16:20	CDR	
16:10-16:35	FE-1	
16:20-16:35	CDR	Private Medical Conference (Ku + S-band)
16:35-17:10	CDR	DINNER
16:35-16:50	FE-1	Private Medical Conference (Ku + S-band)
16:40-17:10	FE-2, FE-2-16	DINNER
16:50-17:20	FE-1	
17:10-18:10	CDR, FE-2, FE-2- 16	Pre-sleep
17:20-18:10	FE-1	
18:10-02:40		SLEEP

Note: 1. See OSTP for references to US activities.

2. SM window #9 shutter opening on crew's discretion3. No Exercise: 14:23 - 15:23

End of Radiogram