Radiogram No. 6862u

## Form 24 for 01/10/08

## Pressurizing and Opening Progress 362 Refueling System Tanks БΓ (O) 1, 2. Opening lines

GMT	CREW	ACTIVITY
06:00-06:10	CDR, FE-2	Morning Inspection
	FE-1	SONOCARD. Experiment (termination)
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45		Prep for Work
07:45-08:00		Morning Planning Conference (S-band)
08:00-08:10	FE-1 CDR, FE-2	Prep for Work
08:00-08:15		
08:15-09:05	FE-2	Environmental Health System (EHS) - water sample analysis
08:15-08:35	CDR	EXPRESS Rack 1 ITCS loop depress
08:15-08:25	FE-1	SONOCARD. Copy data to RSE-MED Laptop
08:25-08:35		Stop discharging the 2nd Battery Pack 825M3 and start discharging the 3rd Battery Pack 825M3
08:35-09:05	CDR	EXPRESS Rack 1 Config for Subsystem Valve R&R
08:35-10:35	FE-1	DC1 comm config Spacesuit and ECC (Orlan interface unit) leak checks and valve tests; backup bladder leak check (suit#26). <i>Tagup (Sband)</i> Restore the nominal comm. configuration
09:05-11:05	CDR	EXPRESS Rack 1 Subsystem Valve R&R
09:05-09:20	FE-2	Assistance in EXPRESS Rack 1 Valve R&R
09:20-10:50	FE-2	Physical Exercise (RED)
10:35-11:35	FE-1	Orlan stow. Tagup (S-band)
11:05-11:20	FE-2	Assistance in EXPRESS Rack 1 Valve R&R
11:05-11:50	CDR	EXPRESS Rack 1 Subsystem Valve Inspection
11:30-12:30	FE-2	Physical Exercise (CEVIS)
11:40-12:20	FE-1	Preparation for donning Penguin suit. Tagup (S-band)
11:50-12:30	CDR	СОЖ Maintenance
12:20-12:30	FE-1	Donning Penguin suit
12:30-13:30		LUNCH
13:30-13:40	FE-1	Downloading data during Penguin suit wearing test
	CDR	FMK deployment ops
13:30-13:35	FE-2	BCAT-3. Camera checkout
13:40-14:10	FE-1	BAR. Hardware transfer, set up, and preparation. Tagup (S-band)
14:00-14:10	CDR	CWC audit
14:05-14:10	FE-2	PAO hardware setup
14:10-14:20		Crew prep for PAO
14:20-14:40		PAO event (S + Ku-band)
14:40-15:40	FE-2	WAP setup
14:40-14:50	FE-1	Downloading data during Penguin suit wearing test
14:50-15:20		BAR. Hardware transfer, set up and preparation

14:50-15:20	CDR FE-1	Crew Medical Restraint System (CMRS) integrity checkout
15:20-16:20		Physical Exercise (TVIS)
15:20-15:30		Downloading data during Penguin suit wearing test
15:30-15:40		Penguin suit closeout ops
15:40-16:40		BAR. ПхО, DC1 Measurements. Data downlink via БСР-ТМ
15:40-16:40	FE-2	Crew PDA reloading
16:20-17:50	CDR	Physical Exercise (RED)
16:40-18:10	FE-2	Deploy PDAs On Wireless Network
16:50-17:50	FE-1	Physical Exercise (TVIS), day 1
18:10-18:15	FE-2	Transfer TVIS/RED/CEVIS/HRM data to MEC
18:15-19:05		Evening work prep
19:05-19:20		Daily Planning Conference (S-band)
19:20-19:30		Evening work prep
19:30-20:00		DINNER
20:00-20:30		Daily Food Prep
20:30-21:30	CDR, FE-2	Pre-sleep
20:30-21:20	FE-1	
21:20-21:30	FE-1	BAR. Kelvin charging
21:30-06:00		SLEEP
Task List	FE-1	IMS update

## Note:

- See OSTP for references to US activities.
  SM Window #9 shutter opening is at crew discretion

End of Radiogram