Leak Check of Fuel Refilling (3УГ) and Oxidizer Refilling Devices (3УО).

| GMT | CREW | ACTIVITY |
|--------------|------|--------------------------------------------------------------------------------------------------|
| 11:30-11:40 | | Morning inspection |
| 11:40-12:10 | | Post-sleep |
| 12:10-13:00 | | BREAKFAST |
| 13:00-13:15 | | Daily planning conference (S-band) |
| 13:15-14:15 | | Progress 355 transfers and IMS update |
| 14:15-14:30 | CDR | PromISS experiment sample transfer to Kubik |
| 14:15-14:50 | FE-1 | CRYSTALLIZER. Transfer to SM, activation and set up in Cryogem-03M |
| 14:50-15:00 | | CRYSTALLIZER. Photo imagery. Tagup with specialists. (S-band) |
| 15:00-15:40 | | ALTCRISS. Hardware transfer and activation. Tagup with specialists (S-band) |
| 15:05-16:35 | CDR | Physical exercise (CEVIS) |
| 15:40-15:50 | FE-1 | ALTCRISS. Photography |
| 15:50-16:30 | | GCF-JAXA. Hardware transfer and set up in TBY thermostat. <i>Tagup with specialists</i> (S-band) |
| 16:30-16:40 | | GCF-JAXA. Hardware photo imagery |
| 16:40-17:40 | | LUNCH |
| 17:40-19:10 | FE-1 | JAXA 3D-PCGF. Transfer and stow hardware in SM. Tagup with specialists. (S-band) |
| 19:05-19:35 | CDR | СОЖ maintenance |
| 19:10-19:20 | FE-1 | JAXA 3D-PCGF. Hardware post-installation photo |
| 19:20-19:40 | | STATOKONIA. Transfer and stow hardware in SM. Tagup with specialists (S-band) |
| 19:35-20:35 | CDR | Physical Exercise (RED) |
| 19:40-20:40 | FE-1 | Physical Exercise (TVIS) Day 4 |
| 20:40-20:45 | | "Sputnik-SM" hardware activation |
| 23. 10 20.40 | CDR | Transferring TVIS, RED, and HRM data to MEC |
| 20:45-21:00 | | Daily planning conference (S-band) |
| 21:00-21:30 | | DINNER |
| 21:30-22:00 | | Daily food prep |
| 22:00-23:00 | FE-1 | Pre-sleep |
| 22:00-22:30 | CDR | 1.10 0.000 |
| 22:30-22:45 | | Private family conference (Ku + S-band) |
| 22:45-23:00 | | Pre-sleep |
| 23:00-07:30 | | SLEEP |

Note: See OSTP for references to US activities.

End of Radiogram