## **RSS2 LAPTOP A31P Installation and Testing**

GMT	CREW	ACTIVITY
08:30-08:40	CDR, FE-2	Morning Inspection
08:30-08:35	FE-1	PLASMA CRYSTAL-3 PLUS. Turbo-pump activation
08:35-08:45	FE-1	Morning inspection
08:40-08:55	FE-2	Post-sleep
08:40-08:55	CDR	Biochemical urine test
08:45-09:15	FE-1	Post-sleep
08:55-09:10	FE-2	Biochemical urine test
08:55-09:25	CDR	Post-sleep
09:10-09:25	FE-2	Post-sleep
09:15-10:05	FE-1	BREAKFAST
09:25-10:15	CDR, FE-2	BREAKFAST
10:05-10:35	FE-1	Prep for Work
10:15-10:35	CDR, FE-2	Prep for Work
10:35-10:50		Daily Planning Conference (S-band)
10:50-12:20	FE-1	Laptop RSS2 installation and testing (replacement of PACKET Laptop). Tagup with specialists (S-band)
10:50-11:00	CDR, FE-2	Prep for Work
11:35-12:35	CDR, FE-2	EVA procedure review
12:20-12:50	FE-1	СОЖ maintenance
12:35-13:20	CDR, FE-2	Equipment Lock config
12:50-13:10	FE-1	Private Family Conference (Ku + S-band)
13:20-14:20	FE-2	Physical Exercise (RED)
13:25-13:35	CDR	Terminate EMU Metox Regeneration
13:35-15:05	FE-1	Physical Exercise (TVIS), Day 3
13:35-15:05	CDR	Physical Exercise (CEVIS)
14:20-14:35	FE-2	Private Family Conference (Ku + S-band)
14:50-15:05	FE-2	Rebooting all PCS (weekly)
15:05-16:05		LUNCH
16:05-16:10	CDR	HAM radio powerdown in FGB
16:20-17:05		EVA procedure review
17:05-17:50		EVA tagup with MCC (S-band)
17:50-18:50	FE-1	Physical Exercise (VELO+RED) day 3
18:25-19:55	FE-2	Physical Exercise (TVIS)
18:50-19:50	CDR	Physical Exercise (RED)
19:30-20:30	FE-1	Evening work prep
19:50-20:25	CDR	Evening work prep
19:55-20:30	FE-2	Evening work prep
20:25-20:30	CDR	Transfer TVIS/RED/CEVIS/HRM data to MEC

20:30-20:45		Daily Planning Conference (S-band)
20:45-20:55	CDR, FE-2	Evening work prep
20:55-21:25		DINNER
21:25-21:55		Daily food prep
21:55-22:10	FE-1	Pre-sleep
21:55-22:25	CDR, FE-2	Pre-sleep
22:10-22:25	FE-1	PILLE dosimeter preparation for EVA
22:25-23:10	FE-1	Start pre-breathe
22:25-23:30	CDR, FE-2	Start pre-breathe
23:10-23:55	FE-1	Pre-sleep
23:30-00:00	CDR, FE-2	Pre-sleep
23:55-00:00	FE-1	PLASMA CRYSTAL-3 PLUS. Turbo-pump deactivation
00:00-08:30		SLEEP
Task List	FE-1	ТБУ (Universal Bioengineering Thermostat). Temperature check
I dok List		Search for CO2 Filter Unit

Note: See OSTP for references to US activities.

End of Radiogram