Radiogram No. 8346u ISS REBOOST USING ATV

Form 24 for 08/13/08

GMT	CREW	ACTIVITY
06:00-06:10	CDR, FE-2	Morning Inspection
06:00-06:10	FE-1	SONOCARD. Experiment termination
06:10-06:20	FE-1	Morning Inspection
06:10-06:15	FE-2	Post-sleep
06:10-06:40	CDR	
06:15-06:20	FE-2	SLEEP - Data Log (FE2)
06:20-06:40	FE-1	Post-sleep
06:20-06:45	FE-2	
06:40-07:30	CDR, FE-1	BREAKFAST
06:45-07:35	FE-2	BREAKFASI
07:30-07:40	FE-1	Post-sleep
07:30-08:00	CDR	Prep for Work
07:35-08:05	FE-2	
07:40-08:10	FE-1	PLASMA-ISS. Activate hardware, set up modes, and run the experiment Tagup with specialists (S-band)
08:05-08:20	CDR, FE-2	Daily Planning Conference (S-band)
08:10-08:20	FE-1	
08:20-09:35	FE-2	FPEF Marangoni Surface Setup 2
08:20-08:35	CDR,Б И-1	Treadmill Vibration Isolation and Stabilization (TVIS) Belt Slat Screw Re- Torque
08:35-08:50	CDR	URAGAN. Observations and Photography
08:35-08:50	FE-1	Prep for Work
08:50-10:05	CDR, FE-1	Replacement of TVIS bearing assembly
09:35-11:05	FE-2	SW Upgrade: Memory Mass Unit Software Load Stage 2
10:05-10:35	CDR, FE-1	Replacement of TVIS bearing assembly
10:35-11:05	FE-1	PLASMA-ISS. Hardware removal Tagup with specialists (S-band)
10:35-11:10	CDR	TVIS Noise Capture
11:05-11:10	FE-1	
11:05-11:15	FE-2	SW Upgrade: Memory Mass Unit Software Load Stage 3
11:10-13:00	FE-1	LULIN. Hardware Set Up For Operation. Tagup with specialists (S-band)
11:10-12:30	CDR	Physical Exercise (TVIS), day 1
11:20-12:20	FE-2	FPEF Marangoni Surface Setup 3
12:20-12:30	FE-2	FMK Stow
12:30-13:00	CDR	TVIS Monthly Maintenance
12:45-13:00	FE-2	FSL Facility Core Element Unlock
13:00-13:20	FE-1	LUNCH
13:00-14:00	CDR, FE-2	
13:20-13:30	FE-1	URAGAN. Observations and Photography
13:30-14:00	FE-1	LUNCH
14:00-14:15	FE-1	SONOCARD. Copy Data to RSE-MED Laptop

14:00-15:35	CDR	Progress 364 Loading and IMS Updates
14:05-14:15	FE-2	PAO Hardware Setup
14:15-14:25	FE-2	Crew Prep for PAO
14:15-14:25	FE-1	PLANTS-2. Photography
14:25-14:40	FE-1	Matryoshka-R. AST Spectrometer PCMCIA Card Replacement and Checkout
14:25-14:45	FE-2	PAO Event (Ku + S-band)
14:40-15:20	FE-1	СОЖ Maintenance
14:45-14:50	FE-2	Software Transition: Portable Work Station 2 Software Reload Step1
14:50-14:55	FE-2	SW Upgrade: Portable Work Station 2 (LAN) Cable Disconnect.
15:00-16:00	FE-2	Software Transition: Portable Work Station 2 Software Reload Step2
15:20-16:20	FE-1	Physical Exercise (VELO+RED), day 1
15:40-16:00	CDR	PILOT-M. Search and configure equipment
16:00-17:00	CDR	Scheduled Test and Screen Photo of Vertical Wide Angle Precision Sight (ВШТВ). <i>Tagup with specialists (S-band)</i>
16:05-16:10	FE-2	HAM Radio Setup
16:10-16:20	FE-2	HAM Radio Session
16:20-17:50	FE-2	Physical Exercise (RED)
16:20-17:50	FE-1	Physical Exercise (TVIS), day 1
17:00-17:20	CDR	IMS Update
17:20-17:55	CDR	Prep for Work
17:50-18:50	FE-2	Physical Exercise (CEVIS)
17:55-18:55	CDR	Physical Exercise (VELO+RED), day 1
18:20-18:50	FE-1	Prep for Work
18:50-18:55	FE-1	Transfer of TVIS, RED, and HRM data to MEC
18:50-18:55	FE-2	Connect JEMRMS RLT Laptop
18:55-19:10		Daily Planning Conference (S-band)
19:10-19:30	CDR, FE-1	Prep for Work
19:10-19:15	FE-2	Backup Control Center (BCC) NetMeeting Checkout
19:15-19:30	FE-2	Prep for Work
19:30-20:00		DINNER
20:00-20:30		Daily Food Prep
20:30-21:30	FE-1	
20:30-21:20	CDR	Pre-sleep
20:30-21:25	FE-2	
21:20-21:30	CDR	SONOCARD. Experiment Start
21:25-21:30	FE-2	Questionnaire - journal entry
21:30-06:00		SLEEP
Task List	FE-1	PLANTS-2. Payload Status Check

- Notes:
 1. SM Window #9 shutter opening is at crew discretion with Report to MCC
 2. See OSTP for references to US activities.
 End of Radiogram