Radiogram No. 6057u **OUTFITTING СУБА CABLE SYSTEM**

GMT	CREW	ACTIVITY
06:00-06:10		Morning Inspection
06:10-06:40		Post-sleep
06:40-07:30		BREAKFAST
07:30-07:45	İ	Daily Planning Conference (S-band)
07:45-08:15	İ	Prep for Work
08:15-09:15	CDR, FE-2	TVIS Periodic Chassis Inspection
08:15-10:35	FE-1	Outfitting of CY5A cabling to install ΠΠC-31. <i>Tagup with specialists (S-band)</i>
09:15-09:45	CDR	Retrieval of Π-16 absorbers from behind SM panel 136 (S/N 10.01-92-01-09, 10.01-92-01-11, 10.01-92-01-06) set up behind SM panel 129
09:15-13:15	FE-2	TVIS Rollerbearing R&R
09:45-11:15	CDR	Physical Exercise (RED)
10:55-11:15	FE-1	PLANTS-1. Data collection and downlink
11:15-12:45	CDR	MPEG-2 coder test from Laptop RSS1. Tagup with specialists (S-band)
11:15-12:45	FE-1	Physical Exercise (RED)
12:45-13:45	CDR, FE-1	LUNCH
13:15-14:15	FE-2	
13:45-17:15	FE-1	Outfitting of CYEA cabling to install ΠΠC-31. Tagup with specialists (S-band)
14:15-15:15	CDR, FE-2	TVIS Periodic Chassis Inspection
15:15-16:15	FE-2	Physical Exercise (RED)
15:15-15:35	CDR	IMS Update
15:35-16:15		СОЖ Maintenance
16:15-17:45	FE-2	Physical Exercise (CEVIS)
17:15-18:15	FE-1	Physical Exercise (VELO) Day 2
	CDR	Prep for Work
17:45-18:00	FE-2	EPO - Plant Photos CWC audit
18:00-18:10		
18:10-19:10	FE-2	Prep for Work
18:15-19:15	FE-1	
18:15-19:15	CDR	Physical Exercise (VELO) Day 2
19:10-19:15	FE-2	Transfer TVIS/RED/CEVIS/HRM data to MEC
19:15-19:30		Daily Planning Conference (S-band)
19:30-20:00		DINNER
20:00-20:30		Daily Food Prep
20:30-21:30		Pre-sleep
21:30-06:00		SLEEP
Task List	FE-1	GCF-JAXA. Tby temperature monitoring (in the morning)

Note: See OSTP for references to US activities. End of Radiogram