Refueling Low-Pressure Fuel Tank (БНДГ(O)1-3) in FGB from fuel tank БГ (O)1,2 СД of Progress #402

Time	Crew	Ops
06:00-06:10	CDR,FE-3,FE-4, FE-5	Morning inspection
06:00-06:05	FE-1,FE-2	SLEEP - data logging
06:05-06:10	FE-1,FE-2	Morning inspection
06:10-06:40		Post-sleep
06:40-07:30	FE-1,FE-2,FE-3, FE-4,FE-5	Breakfast
06:40-07:25	CDR	Breakfast
07:25-07:30	CDR	РАСТЕНИЯ-2. H/w monitoring
07:30-07:55		DPC (S-band)
07:55-08:00	FE-3	Work prep
07:55-08:40	CDR,FE-1	EVA timeline update. Tagup with specialists (S-band)
07:55-08:55	FE-2	PE ARED
07:55-08:05	FE-5	Work prep
07:55-08:10	FE-4	Water Purification System – fill CWC-I from PWD auxiliary port
08:00-10:00	FE-3	Audit hw connected to RS power outlets ΠΠC-26 and ΠΠC-31
08:05-09:35	FE-5	WHC – tank troubleshooting
08:10-08:20	FE-4	PFE video equipment installation
08:20-08:25	FE-4	PLT laptop activation
08:25-08:35	FE-4	Lab windows shutter closing
08:40-08:55	FE-4	Water Purification System – fill CWC-I from PWD auxiliary port
08:40-08:55	CDR	Prepare sealing handles - 2 items. (11Φ732.Γ1021-OA, CM1ΠpK_1, components pack CmA NA_17488, CO1_14_BΠC4, components pack CmA, b/c 005501R) and hw to secure covers in ΠxO – 4-6 rubber retention devices (CO1ЦC, 1.0 CTB 1159)
08:55-09:25	FE-2	BRT tether inspection
09:00-10:30	FE-4	Periodic fitness check – nom ops
09:10-09:55	FE-1,CDR	Depress/Repress procedure review. Tagup with specialists (S-band)
09:25-10:55	FE-2	Packing US EVA tools
09:35-10:05	FE-5(мощь)	Periodic fitness check – nom ops
09:55-10:10	CDR	Prepare Pille sensors for EVA
10:00-10:10	FE-3	Verifying absence of cooling agent on housing of half-coupling 4F64 KO62
10:05-10:15	FE-5	WRS – water samples analysis
10:10-10:30	FE-3	Inspect residue trap insert in CPB-K2M
10:10-10:25	CDR	Prepping medkit for EVA-23
10:20-10:30	FE-5	ICV – materials review
10:25-10:35	CDR	РАСТЕНИЯ-2. Photographing plants
10:30-11:10	FE-3	COЖ maintenance

10:30-11:00	FE-5	ICV – operator reviews materials
10:30-10:40	FE-4	PFE – video equipment stowing
10:35-10:45	CDR	РАСТЕНИЯ-2. Data downlink
10:40-10:50	FE-4	Procedure review before first experiment run
10:50-11:00	CDR	РАСТЕНИЯ-2. Data downlink
10:50-11:00	FE-4	Procedure review for assisting crewmember before experiment run
10:55-12:25	FE-2	Prepping tools for EVA
11:00-11:30	FE-4,FE-5	ICV – crew conference
11:10-11:30	FE-3	IMS update
11:30-12:30	FE-5	PE ARED
11:30-12:30	FE-4	PE CEVIS
11:45-12:00	CDR	PMC (S+Ku-band)
11:45-12:15	FE-3	ВЗАИМОДЕЙСТВИЕ. Experiment run. <i>Tagup with specialists (S-band)</i>
12:25-12:30	FE-2	TVIS CEVIS HRM data transfer to MEC
12:30-13:00	FE-4	Lunch
12:30-13:30	CDR,FE-3,FE-5	Lunch
12:30-12:45	FE-5	Lunch
12:30-12:45	FE-1	PMC (S-band)
12:30-13:30	FE-2	Lunch
12:45-13:30	FE-1	Lunch
12:45-13:00	FE-5	PMC (S-band)
13:00-13:30	FE-5	Lunch
13:00-13:15	FE-4	PMC (S-band)
13:15-13:30	Lunch	Lunch
13:30-13:40	FE-5	TOCA – data transfer
13:30-14:00	CDR,FE-1,FE-2, FE-3,FE-4	Pre-sleep
13:40-14:00	FE-5	Pre-sleep
14:00-23:00		Sleep

Notes:

- 1 Window 9 cover opening crew discretion, Report to MCC
 2. Missing links to US ops -- see OSTP
 3. Tagup with EVA specialists with all other activities in the background (S-band + VHF) End of Rg