Rose Excellence Corporation San Francisco, Agusan del Sur		CHILLER STANDARD OPERATING PROCEDURE		
Department	PRODUCTION	Revision No.	0	
Type of Document	WORK INSTRUCTION	Issue No.	1	
Document No.	REC-PD-M-05	Effective Date		Page 1 OF 4

DISTRIBUTION LIST

DCBS 1 - Office of the President	**DCBS 1** - Operations	**DCBS 1** - Admin Office

REVISION HISTORY

DCN No.	EFFECTIVITY DATE	ISSUE NO.	REV. NO.	PAGE AFFECTED	DETAILS OF CHANGE	ORIGINATOR
		1	0	ALL	FIRST ISSUE PER QMS	WILMAR M. MARFIL

REVISION LEVEL

PAGE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
REV.																		

	NAME	POSITION	SIGNATURE
Authored by:	WILMAR M. MARFIL	Production Division Head	
Reviewed by:	MELINA G. COMEDIDO	COO	
Approved by:	MANUELITO O. GO	PRESIDENT / CEO	

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

1. PURPOSE

To establish work instruction procedures for all ovens used both at commissary and branch levels and to achieve the expected output in terns of quality, safety and quantity.

2. SCOPE

This Work Instruction covers the Standard Operating Procedures (SOP) of all conventional ovens being used at all facilities of Rose Excellence Corporation.

3. DEFINITION OF TERMS

TERMS	DEFINITION
Power Cord	**A cord connected to the machine and is used to Power it ON or OFF.**
AVR	Automatic Voltage Regulator. Serves as protection for compressor.
Back Light	Indicator light of AVR.

4. TURNING ON PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
PLUG AC POWER PLUG.	**Plug in the power cord at a safe convenience outlet. Ensure no breakage, exposed wirings before plugging the power cord. Ensure terminal wires are properly connected on the male prong and not loose.**	**Operator**

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
	Turn ON the Automatic Voltage Regulator (AVR). Ensure there is backlight and the gauge is working.	**Operator**
	Turn ON the temperature from panel display of the machine. Ensure to set it between 3-5°C	**Operator**
	Switch on the light to illuminate the chiller. Ensure no excessive water dripping inside the chiller and no excessive fogging.	**Operator**
	Clean the chiller to make as part of the 5S compliance.	**Operator**

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

5. TURNING OFF PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
	Turn OFF the chiller machine from the panel (ONLY AS NEEDED).	**Operator**
	Switch OFF the voltage regulator. Ensure that the backlight is OFF.	**Operator**
	**Unplug the power cord. Ensure to hold on the head of the power cord to properly unplug.**	**Operator**
	Clean the chiller properly.	**Operator**

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.