DISTRIBUTION LIST

DCBS 1 - Office of the President	**DCBS 1** - Operations	**DCBS 1** - Admin Office

REVISION HISTORY

DCN No.	EFFECTIVITY DATE	ISSUE NO.	REV. NO.	PAGE AFFECTED	DETAILS OF CHANGE	ORIGINATOR
		1	0	ALL	FIRST ISSUE PER QMS	WILMAR M. MARFIL

REVISION LEVEL

PAGE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
REV.																		

	NAME	POSITION	SIGNATURE
Authored by:	WILMAR M. MARFIL	Production Division Head	
Reviewed by:	MELINA G. COMEDIDO	COO	
Approved by:	MANUELITO O. GO	PRESIDENT / CEO	

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

1. PURPOSE

To establish work instruction procedures for all ovens used both at commissary and branch levels and to achieve the expected output in terns of quality, safety and quantity.

2. SCOPE

This Work Instruction covers the Standard Operating Procedures (SOP) of all conventional ovens being used at all facilities of Rose Excellence Corporation.

3. DEFINITION OF TERMS

TERMS	DEFINITION
Power Cord	A cord connected to the machine and is used to Power it ON or OFF.
Rolling Pins	A lever that is used to flatten the dough.
Power Knob	Device use to turn ON and OFF the machine.
Scraping	A process of removing dough deposits on rolling pins and bed.

4. TURNING ON PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
	Before starting, ensure the rolling pins at rest position have enough clearance that would fit your thumb from end to end.	Operator

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
 PLUG AC POWER PLUG.	Plug in the power cord at a safe convenience outlet. Ensure no breakage, exposed wirings before plugging the power cord. Ensure terminal wires are properly connected on the male prong and not loose.	Operator
	Activate the power knob to turn ON the machine. Ensure even rotation of the rolling pins and no abnormal sound.	Operator
	Start rolling operation by beginning at the largest gap slowly narrowing it so that the machine will not be over-loaded. Ensure FULL FOCUS while undergoing this process.	Operator
	Make the necessary adjustment to achieve the consistency of dough.	Operator

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

5. TURNING OFF PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
	After rolling, ensure to unplug the power cord from the outlet.	**Operator**
	**Scrape and clean bot the rolling pins and remove excess materials from the nearby area.**	**Operator**
	Clean the rolling bed of excess debris from the previous operation.	**Operator**
	Ensure this cleanliness of rolling machine after use.	**Operator**

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.