Rose Excellence Corporation San Francisco, Agusan del Sur		SLICER STANDARD OPERATING PROCEDURE		
Department	PRODUCTION	Revision No.	0	
Type of Document	WORK INSTRUCTION	Issue No.	1	
Document No.	REC-PD-M-03	Effective Date		Page 1 OF 4

DISTRIBUTION LIST

DCBS 1 - Office of the President	**DCBS 1** - Operations	**DCBS 1** - Admin Office

REVISION HISTORY

DCN No.	EFFECTIVITY DATE	ISSUE NO.	REV. NO.	PAGE AFFECTED	DETAILS OF CHANGE	ORIGINATOR
		1	0	ALL	FIRST ISSUE PER QMS	WILMAR M. MARFIL

REVISION LEVEL

PAGE	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18
REV.																		

	NAME	POSITION	SIGNATURE
Authored by:	WILMAR M. MARFIL	Production Division Head	
Reviewed by:	MELINA G. COMEDIDO	COO	
Approved by:	MANUELITO O. GO	PRESIDENT / CEO	

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

1. PURPOSE

To establish work instruction procedures for all ovens used both at commissary and branch levels and to achieve the expected output in terns of quality, safety and quantity.

2. SCOPE

This Work Instruction covers the Standard Operating Procedures (SOP) of all conventional mixers being used at all facilities of Rose Excellence Corporation.

3. DEFINITION OF TERMS

TERMS	DEFINITION
Power Cord	A cord connected to the machine and is used to Power it ON or OFF.
Slide Board	A flat bed where loaf bread are paced for cutting.
Rocker Switch	An ON/OFF toggle switch
Vibrating	An action or actuation of the machine to slide down loaf bread for cutting.
Cord Head	The head of power cord where 2 pins are connected.

4. TURNING ON PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
PLUG AC POWER PLUG.	Plug in the power cord at a safe convenience outlet. Ensure no breakage, exposed wirings before plugging the power cord. Ensure terminal wires are properly connected on the male prong and not loose.	Operator

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
PUT BREAD TO BE SLICED.	Carefully place loaf bread on the slide board ensuring flatness and not tilted.	Operator
TURN ON POWER SWITCH TO START.	Push rocker switch to activate the machine. Once ON, take note to push inward slowly the loaf on the vibrating board for cutting.	Operator
TURN OFF POWER SWITCH TO STOP.	Set the rocker switch to OFF after done with first batch of loaf breads. Ensure to check tightness of guideboard and plate from time to time.	Operator

5. TURNING OFF PROCEDURE

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
TURN OFF POWER SWITCH TO STOP.	Set the rocker switch to OFF after done with first batch of loaf breads. Ensure to check tightness of guideboard and plate from time to time.	Operator

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.

ILLUSTRATION	CRITICAL PARAMETER	RESPONSIBLE
	Unplug the power cord from the outlet. Ensure to hold on the head of the power cord not on the wire to avoid damage.	**Operator**
	Ensure to properly clean work station after use.	**Operator**

Any hard copy of this document without the signed first page or unprotected soft copy is regarded as an uncontrolled copy. No part of the publication should be used or reproduced in any form or by any means, or stored in a database or retrieval without prior written permission of the Quality Management Representative.