#### **Table of Contents**

Determine a Homogeneous Transformation matrix	
multiplication of matrices to obtain the position of the links	
Determining the constants and random values of joint coordinates in the ranges	
Subtitute random generated ranges into the matrices	4
Defining origin and constant position of the 1st link	4
Draw the workspace	1

3rd laboratory task

Piotr Bury, Maciej Paczocha

## **Determine a Homogeneous Transformation matrix**

```
clear all; clc
% declaration of symbols
syms th1 d1 th2 a3 th4 d5 q1 q2 q3
% Determination of a symbolic form of HT matrices - application of mA function
A1=mA(th1,d1,0,sym(pi/2));
A2=mA(th2,0,0,0);
A3=mA(0,0,a3,0);
A4=mA(th4,0,0,sym(pi/2));
A5=mA(sym(pi/2),d5,0,0);
```

## multiplication of matrices to obtain the position of the links

```
T01=A1;
T05=A1*A2*A3*A4*A5;
```

## Determining the constants and random values of joint coordinates in the ranges

```
input constants
```

```
d1_input = 0.4;
d5_input = 0.15;
% Random selection of the values of joint coordinates
th1_input = pi/2-pi*rand;
th2_input = pi/4-(pi/2)*rand;
```

```
a3_input=0.6-rand*0.4;
th4 input = pi/2-(pi)*rand;
```

## Subtitute random generated ranges into the matrices

```
T01_real=subs(T01,{th1,d1},{th1_input,d1_input});
T05_real=subs(T05,{th1,d1,th2,a3,th4,d5},{th1_input,d1_input, th2_input, a3_input,
% Calculation of orientation of the 3rd link in relation to the 4th link
%
P_real = [T05_real(1,4); T05_real(2,4); T05_real(3,4)];
Pw = [T05_real(1,3);T05_real(2,3);T05_real(3,3)]*d5_input;
```

## Defining origin and constant position of the 1st link

```
origin = [0 0 0];
joint1 = [T01(1,4) T01(2,4) T01(3,4)];
% Position of joint1 remains constant as it's only dependent from d1 constant vari
% joint2 position cannot be distinguished as it wouldn't be visible in the
% workspace visualization
```


#### **Draw the workspace**

```
x=[0 \ 0.02 \ 0.04 \ 0.06 \ 0.08 \ 0.1 \ 0.12 \ 0.14 \ 0.16 \ 0.18];
y=[0.95 0.97 0.99 1.01 1.03 1.05 1.07 1.09 1.11 1.13];
z=[0.75 \ 0.77 \ 0.79 \ 0.81 \ 0.83 \ 0.85 \ 0.87 \ 0.89 \ 0.91 \ 0.93];
path=[x; y; z];
figure(1);
plot3(x,y,z,'--r')
for i=1:10
    joint4=path(:,i)'
    joint3=joint4-Pw'
    joint1=[T01_real(1,4) T01_real(2,4) T01_real(3,4)]
    pts34=[joint4; joint3];
    pts13=[joint3; joint1];
    pts01=[joint1; origin];
    line(pts34(:,1), pts34(:,2),pts34(:,3));
    line(pts13(:,1), pts13(:,2),pts13(:,3));
    line(pts01(:,1), pts01(:,2),pts01(:,3));
end
         joint4 =
                                   0.95
                       0
                                                 0.75
         joint3 =
```

-0.00	0.95	0.90	
joint1 =			
0	0	0.40	
joint4 =			
0.02	0.97	0.77	
joint3 =			
0.02	0.97	0.92	
joint1 =			
0	0	0.40	
joint4 =			
0.04	0.99	0.79	
joint3 =			
0.04	0.99	0.94	
joint1 =			
0	0	0.40	
joint4 =			
0.06	1.01	0.81	
joint3 =			
0.06	1.01	0.96	
joint1 =			
0	0	0.40	
joint4 =			

	0.08	1.03	0.83
joint3 =			
	0.08	1.03	0.98
joint1 =			
	0	0	0.40
joint4 =	0.10	1.05	0.85
joint3 =			
JOINES -	0.10	1.05	1.00
joint1 =			
	0	0	0.40
joint4 =			
	0.12	1.07	0.87
joint3 =			
	0.12	1.07	1.02
joint1 =	0	0	0.40
joint4 =	J	Ţ.	3.1.3
J0111C4 -	0.14	1.09	0.89
joint3 =			
	0.14	1.09	1.04

joint1 =			
	0	0	0.40
joint4 =			
	0.16	1.11	0.91
joint3 =			
	0.16	1.11	1.06
joint1 =			
	0	0	0.40
joint4 =			
	0.18	1.13	0.93
joint3 =			
	0.18	1.13	1.08
joint1 =			
	0	0	0.40



Published with MATLAB® 8.0