

CAD








Petros Sklavounos

1st Try: Incomplete, flow didn't reach rings










The weird blue nerf bullets are the boundary conditions of the walls which I could not suppress when viewing results.



Flow Volumetric Shrinkage

Ease of injection Second Attemmp: 901 seconds, he atted walls and multiple inlets to prevent premature cooling, reached entirety