


Generator Designs


Design Option 1:

Spinning magnet surrounded by 4–8 sets of wired coils.




Design Option 2:

Rotational plate with 4–8 sets of wired coils surrounding a fixed magnet stick.



Design Option 3:

Rotating magnet stick through shaft placed a small distance in front of the wired coil.



Considered Factors:

1. Number of turns of wire in the coil (the higher number of turns the more voltage induced)
2. Strength of the magnetic field. (Since the magnets are small, providing less magnet field strength, hence the increasing number of used magnets can induce more voltage)
3. Relative speed motion between magnet and coil. (This depends on the gearbox/gear system design)

Housing material:

Wood sheet? As wired coil will generate heat and wood has low heat conduction hence it will protect other components from being overheat.