

## Continuity test

Check continuity between points connected in the two images:

## **3.3V** net



## GND net



## Smoke test

Supply 3.3V power to highlighted test points. Verify all boards have similar (+/-10%) current draw.

