



Sensores y Laboratorio 2019-I


Ing. Juan Ricardo Clavijo Mendoza MSc.



















Span (Full-Scale Input)

Full-Scale Output

Accuracy

Calibration Error

Hysteresis

Nonlinearity

Saturation

Repeatability

Dead Band


Resolution






































































Output Impedance













Zero-Order

First-Order

$$b_1 \frac{\mathrm{d}E(t)}{\mathrm{d}t} + b_0 E(t) = s(t)$$

Second-Order

$$b_2 \frac{d^2 E(t)}{dt^2} + b_1 \frac{dE(t)}{dt} + b_0 E(t) = s(t)$$










First-Order











Second-Order

