
Measurement Schedules: $m = 6$ sensors (window steps 1–12, firing at step 13)
τ_{latency}
t_f
Consecutive
End-Clustered
Uniform Spread
Geometric
Chebyshev
Two-Anchor D-opt.
$\tau_r = 7$ ms
$\tau_r = 1$ ms
$\tau_r = 1$ ms
$\tau_r = 1$ ms
$\tau_r = 1$ ms
$\tau_r = 1$ ms
1
2
3
4
5
6
7
8
9
10
11
12
13
Measurement step ($\times \Delta t = 1$ ms)