```
function cval = x (rate)
c01=1;
c02=2;
c03=1;
c04=2;
c06=1;
c07=1;
c08=1;
r12=6;r15=2;r23=5;r26=5;r36=8;r41=5;r45=1;r48=1;
r52=1;r58=2;r59=1;r69=15;r74=4;r87=2;r89=3;
r01=rate(1);
r02=rate(2);
r03=rate(3);
r04=rate(4);
r06=rate(5);
r07=rate(6);
r08=rate(7);
cval = zeros(1,9);
val1=1;val2=0.0005;iter=0;
while max(val1) > val2 && iter < 25</pre>
ovalue = cval;
```

```
cval(1) = (r01*c01+r41*cval(4))/(r12+r15);
cval(2) = (r02*c02+r12*cval(1)+r52*cval(5))/(r23+r26);
cval(3) = (r03*c03+r23*cval(2))/r36;
cval(4) = (r04*c04+r74*cval(7))/(r41+r48+r45);
cval(5) = (r15*cval(1)+r45*cval(4))/(r52+r58+r59);
cval(6) = (r06*c06+r26*cval(2)+r36*cval(3))/r69;
cval(7) = (r07*c07+r87*cval(8))/r74;
cval(8) = (r08*c08+r58*cval(5)+r48*cval(4))/(r87+r89);
cval(9) = (r59*cval(5)+r69*cval(6)+r89*cval(8))/r90;
val1 = abs((cval-ovalue)./cval)*100;
fprintf(' concentration of each tank\n %d = %.4f q/L\n',[1:9;cval])
end
end
Not enough input arguments.
Error in HW6_3 (line 28)
r01=rate(1);
```

Published with MATLAB® R2021b