


Figure A7 — Sensitivity Analysis: Hyperparameter Choices

A. Sensitivity to Bone Loss Weight



B. Sensitivity to Bone Mask Thickness

