October 22, 2026

VIA EMAIL

Mike Boland, CEO
Linear Motion
628 North Hamilton Street
Saginaw, Michigan 48602

SRN: B3607, Saginaw County

Dear Mike Boland:

VIOLATION NOTICE

On August 13, 2026, the Department of Environment, Great Lakes, and Energy (EGLE), Air Quality Division (AQD) conducted an inspection of Linear Motion (Company) located at 628 North Hamilton Street, Saginaw, Michigan. The purpose of this inspection was to determine the Company's compliance with the requirements of the federal Clean Air Act; Part 55, Air Pollution Control, of the Natural Resources and Environmental Protection Act, 1994 PA 451, as amended, MCL 324.5501 *et seq*; the Air Pollution Control Rules, Mich Admin Code, R 336.1101 *et seq*; and the conditions of Permit to Install (PTI) No. 383-08A.

Violations:

During the inspection, the following violations were observed:

Process Description	Permit/Rule Violated	Comments
Plating	PTI No. 383-08A, EUPLATING, Special Conditions (SC) VI.2 and VI.3	Monitoring/Recordkeeping – Failure to monitor and record the two plating lines scrubber systems operational parameters on a continuous basis.
Paint booth	PTI No. 383-08A, EUPAINTBOOTH, SC VI.3	Monitoring/Recordkeeping – Failure to keep required records of coating usage and emissions on a monthly basis.

Process Description	Permit/Rule Violated	Comments
Paint booth	PTI No. 383-08A, EUPAINTBOOTH, SC VI.4	Monitoring/Recordkeeping – Failure to keep required records of purge / clean-up solvents and emissions on a monthly basis.
Paint booth	PTI No. 383-08A, EUPAINTBOOTH, SC VI.5	Monitoring/Recordkeeping – Failure to keep required records of material usage and emissions on a daily basis.
Paint booth	PTI No. 383-08A, EUPAINTBOOTH, SC VI.6	Monitoring/Recordkeeping – Failure to keep required records for usage of ethylbenzene containing materials and emissions on a monthly basis.
Parts washers	PTI No. 383-08A, FGPARTSWASHER, SC IV.2	Design/Equipment Parameters – Lids on parts washers are left open.
Parts washers	PTI No. 383-08A, FGPARTSWASHER, SC VI.2	Monitoring/Recordkeeping – Information about parts washers are not kept.
Parts washers	PTI No. 383-08A, FGPARTSWASHER, SC VI.3	Monitoring/Recordkeeping – Failure to maintain monthly solvent usage records and emissions calculations.
Parts washers	PTI No. 383-08A, FGPARTSWASHER, SC VI.6	Monitoring/Recordkeeping – Failure to maintain records of solvent usage

Process Description	Permit/Rule Violated	Comments
		on a monthly and 12-month rolling basis.
Facility-wide – hazardous air pollutants	PTI No. 383-08A, FGFACILITY, SC VI.2	Monitoring/Recordkeeping – Failure to maintain calculations and records of individual and aggregate hazardous air pollutants.
Nitric passivation	R 336.1201(2) (Rule 201)	Permit Needed – Nitric passivation operation was modified to a larger size with a corresponding increase in throughput.
Swab painting	Rule 201	Permit Needed – Swab coating is being conducted without a permit and records are not being kept for potential use of permit exemption R 336.1287(2)(c).

The company was issued PTI No. 383-08A on March 21, 2024. An inspection was conducted August 21, 2025, to determine compliance with the permit. A violation notice was issued October 25, 2025, which listed numerous items. In response to the violation notice, the Company submitted a compliance plan on November 7, 2025, detailing the steps and timeframes it was going to take to rectify the situation.

A follow up inspection was conducted August 13, 2026. During this inspection, it was noted the compliance plan submitted on November 7, 2025, was not implemented. Additionally, the nitric passivation process was modified, with a corresponding throughput increase prior to obtaining an air use permit.

In other words, the Company has been in non-compliance with many of the conditions in its permit since the day of issuance and has in fact compounded the situation by

making process modifications which trigger the need for permitting action prior to making changes.

During this inspection, it was noted that the Company had modified permitted equipment and commenced operation of an unpermitted process at this facility. The Company was advised during this inspection, this is a violation of Rule 201. Rule 201 requires that a permit be obtained prior to installation, construction, operation, reconstruction, relocation, or alteration of any process or process equipment which may be a source of an air contaminant.

A program for compliance may include a completed PTI application for the nitric passivation and swab painting process equipment. An application form is available in MiEnviro Portal.

Next Steps:

A written response should be submitted through MiEnviro Portal by **November 12, 2026,** and include all of the following:

- the dates the violations occurred;
- an explanation of the causes and duration of the violations;
- whether the violations are ongoing;
- a summary of the actions that have been taken and are proposed to be taken to correct the violations; and
- the dates by which these actions will take place; and what steps are being taken to prevent a reoccurrence.

If the Company believes the above observations or statements are inaccurate or do not constitute violations of the applicable legal requirements cited, provide appropriate information to explain your position in your response to this letter.

Thank you for your attention to resolving the violations cited above and for the cooperation that was extended to me during my inspection. If you have any questions

regarding the violations or the actions necessary to bring this facility into compliance, please contact me at the number listed below.

Sincerely,



Ben Witkopp
Environmental Engineer
Air Quality Division
989-295-1612

cc: Stephanie Kuerbitz, Linear Motion
Annette Switzer, EGLE
Christopher Ethridge, EGLE
Brad Myott, EGLE
Jenine Camilleri, EGLE
Gina McCann, EGLE