

PUBLISHED: 29-SEP-2014
2014.0 RANGE ROVER (LG), 501-12

INSTRUMENT PANEL AND CONSOLE - LONG WHEELBASE

REAR FLOOR CONSOLE UPPER TRIM - AUTOBIOGRAPHY BLACK (G1716294)

REMOVAL



CAUTION:

Care must be taken not to damage the component.



NOTE:


Some variation in the illustrations may occur, but the essential information is always correct.

1.




CAUTION:

Make sure the doors are in the fully open and down position. Failure to follow this instruction may result in damage to the door veneers.



-
2. Refer to: Rear Floor Console Lower Stowage Compartment Lid (501-12, Removal and Installation).

-
- 3.




Repeat procedure for the other side.


4.

⚠ CAUTION:

Care must be taken not to damage the component.



Repeat procedure for the other side.




6.



WARNING:

Care must be taken not to damage the component.



Repeat procedure for the other side.

7.




WARNING:

Care must be taken when removing and installing the trim panel. The veneer substrate is easily damaged.




CAUTION:


Care must be taken not to damage the surrounding components.



8.



9.






Torque: 1 Nm

10.



CAUTION:

Care must be taken not to damage the component.



INSTALLATION

1.

NOTE:

Install the trim retaining clips in the moulding prior to installing the components.



-
2. To install, reverse the removal procedure.