

2016.0 RANGE ROVER (LG), 501-09

REAR VIEW MIRRORS

EXTERIOR MIRROR MOTOR

[G1551635]

REMOVAL AND INSTALLATION

REMOVAL

NOTES:


- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.

1. Refer to: [Exterior Mirror Glass](#) (501-09 Rear View Mirrors, Removal and Installation).

2.

CAUTION:

Take extra care not to damage the component.



E133284

Torque: 1.2 Nm

INSTALLATION

1. To install reverse the removal procedure.