

2016.0 RANGE ROVER (LG), 501-10

SEATING - LONG WHEEL BASE

REAR SEAT FORWARD/REARWARD MOTOR - VEHICLES WITH: REAR BUSINESS SEATS (G1545816)

REMOVAL AND INSTALLATION

REMOVAL

NOTE:


Removal steps in this procedure may contain installation details.

1. Refer to: [Rear Seat Massaging Lumbar Assembly - Vehicles With: Rear Business Seats](#) (501-10B Seating - Long Wheel Base, Removal and Installation).

2.


NOTES:

- Make sure the wiring harness is routed correctly.
- Some variation in the illustrations may occur, but the essential information is always correct.




Torque: 40 Nm


3.



4.




5.



6.

NOTE:



Some variation in the illustrations may occur, but the essential information is always correct.



7.


NOTE:

Some variation in the illustrations may occur, but the essential information is always correct.




E145124

8.





E145214

9.





10.




E145213

11.




Torque: 5 Nm

12.



E146596

13.



INSTALLATION

1. To install, reverse the removal procedure.