


2016.0 RANGE ROVER (LG), 501-29

SIDE PANEL SHEET METAL REPAIRS

DESCRIPTION AND OPERATION

SIDE SERVICE PANELS



E146644

NOTE:

The illustration may indicate either hand of the service panel, the opposite hand will be similar.

1	B-Pillar Inner Panel
2	B-Pillar Reinforcement
3	B-Pillar Outer Panel
4	Side Panel
5	Rocker Panel
6	Rocker Panel Inner Reinforcement
7	A-Pillar Reinforcement

TIME SCHEDULES, SIDE PANELS

The following information shows the total time taken to install single panels. These times do not include removal of mechanical, electrical and trim, (MET), items or paint times.

The times shown are to be used as a guide only.

Single panel times

PANEL DESCRIPTION	HOURS
B-Pillar Inner Panel	15.70
B-Pillar Reinforcement	6.80
B-Pillar Outer Panel	6.20
Side Panel	11.50
Rear quarter panel front wheel housing	6.20
Rocker Panel	8.00

A-Pillar Reinforcement	8.70
Side Panel Front Section	3.30
Rocker Panel Section	0.90