

2016.0 RANGE ROVER (LG), 501-20

SUPPLEMENTAL RESTRAINT SYSTEM

DRIVER AIRBAG MODULE

[G1521673]

REMOVAL AND INSTALLATION

REMOVAL

WARNINGS:

- Allow a period of 10 minutes to elapse after disconnecting the battery before undertaking any work on the SRS.
- Always wear safety glasses when repairing an air bag supplemental restraint system (SRS) vehicle and when handling an air bag module.
- Take extra care when handling supplemental restraint system (SRS) components.
- To avoid accidental deployment and possible personal injury, the backup power supply must be depleted before repairing or replacing any air bag supplementary restraints system (SRS) components. To deplete the backup power supply energy, disconnect the battery ground cable and wait for one minute. Failure to follow this instruction may result in personal injury.
- Always disconnect both battery cables before beginning work on the SRS system. Disconnect the ground cable first. Never reverse connect the battery.
- Make sure all personnel are a minimum of 15 Meters (50 Feet) away from the SRS component. Failure to follow this instruction may result in personal injury.
- When repairing an SRS system, only use genuine new parts.

CAUTION:

Make sure the wires are not twisted before connecting them to the airbag module. Once connected do not rotate the airbag as this will cause the wires to twist, which can lead to harness damage and SRS faults.

NOTES:


- Some variation in the illustrations may occur, but the essential information is always correct.
- If the SRS component is to be replaced, the bar code of the new unit must be recorded.

1. Refer to: [Specifications](#) (414-01 Battery, Mounting and Cables, Specifications).

2.

NOTE:

The steering wheel is shown removed for clarity.




E149037

3.


NOTE:

Component shown removed for clarity.





E155438

4.



E149038

5.




E149039

6.

CAUTION:

Take extra care not to damage the wiring harnesses.




E149610

INSTALLATION

1.

CAUTION:

Take extra care not to damage the wiring harnesses.



E149610



2.

WARNING:

Driver air bag module installation can be confirmed by hearing 3 audible clicks, 1 for each clip.

CAUTION:

Take extra care not to damage the wiring harnesses.



E149040

3. If a new component has been installed, configure using Land Rover approved diagnostic equipment.

