

2016.0 RANGE ROVER (LG), 211-05

STEERING COLUMN SWITCHES

STEERING COLUMN MULTIFUNCTION SWITCH

[G1509128]

REMOVAL AND INSTALLATION


86.65.55		SWITCH - COMBINED TURN SIGNAL INDICATOR/HEADLAMP/HORN - RENEW	ALL DERIVATIVES	0.1	USED WITHINS	+
----------	--	--	--------------------	-----	-----------------	---

REMOVAL


NOTE:

Removal steps in this procedure may contain installation details.


1.



2.



3.



E148431

INSTALLATION

1. To install, reverse the removal procedure