

2016.0 RANGE ROVER (LG), 412-02

AUXILIARY CLIMATE CONTROL

FUEL FIRED BOOSTER HEATER OVERHEAT SENSOR

[G1604773]

REMOVAL AND INSTALLATION

REMOVAL

NOTE:

Removal steps in this procedure may contain installation details.


1. Refer to: [Fuel Fired Booster Heater Control Module](#) (412-02A Auxiliary Climate Control, Removal and Installation).

2.




E155487

3.



E155485


4.



5.

NOTE:

Remove the terminals from the connector as indicated in order to replace the component.



E155484

1. To install, reverse the removal procedure.