

2016.0 RANGE ROVER (LG), 415-01

INFORMATION AND ENTERTAINMENT SYSTEM

ROOF POD [G1816038]

REMOVAL AND INSTALLATION

REMOVAL

NOTES:

- Some variation in the illustrations may occur, but the essential information is always correct.
- Removal steps in this procedure may contain installation details.

1.

NOTE:

The procedure must be carried out on both sides.

Refer to: [Sun Visor](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

2.

NOTE:

The procedure must be carried out on both sides.

Refer to: '[A](#)' [Pillar Trim Panel](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

3.

NOTE:

The procedure must be carried out on both sides.

Refer to: '[B](#)' [Pillar Center Trim Panel](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

4.

NOTE:

The procedure must be carried out on both sides.

Refer to: '[C](#)' [Pillar Upper Trim Panel](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

5.

NOTE:

The procedure must be carried out on both sides.


Refer to: '[D](#)' [Pillar Trim Panel](#) (501-05 Interior Trim and Ornamentation, Removal and Installation).

6. Refer to: [Overhead Console](#) (501-12A Instrument Panel and Console - Standard Wheel Base, Removal and Installation).

7.

NOTE:

Note the orientation of the seal prior to detaching.




E158940

8.

NOTE:

The step must be carried out on both sides.




E156888

Torque: 6 Nm

9.

NOTE:

The step must be carried out on both sides.




Torque: 6 Nm

10.

NOTE:

The step must be carried out on both sides.




E156894

11.

NOTE:

The step must be carried out on both sides.




E156896

Torque: 6 Nm

12.

NOTES:

- The step must be carried out on both sides.
- If equipped.



E158900

13.

NOTES:

- The step must be carried out on both sides.
- If equipped.



Torque: 6 Nm


14.

CAUTION:

Take extra care not to damage the component.

NOTE:

The step must be carried out on both sides.




15.

CAUTIONS:


- Take extra care not to damage the component.
- Using a suitable plastic trim tool, release the magnetic fixings.

NOTE:

Make sure that there is at least 50mm clearance between the magnetic fixings and the headliner during the removal procedure. The fixings will engage if too close to each other.




16.



17.

CAUTION:

Take extra care not to damage the component.




E162310

18.



E165562

19.



INSTALLATION

1. To install, reverse the removal procedure.