

2016.0 RANGE ROVER (LG), 413-09

WARNING DEVICES

SERVICE INDICATOR RESET

[G1717023]

GENERAL PROCEDURES

SYNCHRONIZATION

NOTE:

Make sure the Land Rover approved diagnostic equipment is not connected to the vehicle.

1. Set the ignition to the ON position.
2. Open the hood.
3. Open the drivers door.

4.

NOTE:

A service resetting message will appear on the instrument cluster.

Fully depress both the accelerator and brake pedals and hold for 10

seconds.

5. Set the ignition to the OFF position.
6. Set the ignition to the ON position and check the message has been cleared.
7. If the message remains, repeat the process.