

PUBLISHED: 22-OCT-2013
2015.0 RANGE ROVER (LG), 303-05

ACCESSORY DRIVE - TDV8 4.4L DIESEL

ACCESSORY DRIVE BELT (G1509478)

REMOVAL AND INSTALLATION

86.10.03	DRIVE BELT - GENERATOR - RENEW	4400 CC, TDV8	0.5	USED WITHINS	
----------	---	------------------	-----	-----------------	--

REMOVAL




NOTES:

- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.

1. Disconnect the battery ground cable.
Refer to: [Specifications](#) (414-00 Battery and Charging System - General Information, Specifications).


2. Refer to: [Left Air Cleaner Outlet Pipe](#) (303-12E Intake Air Distribution and Filtering - TDV8 4.4L Diesel, Removal and Installation).

3.




E142592


4.




E142437

5.






7.




Torque: 10 Nm

8.



9.




Torque: 10 Nm

10.

ⓘ CAUTIONS:

- Make sure that the accessory drive belt is correctly seated in all of the pulley grooves.
- Make sure that the accessory drive belt is correctly routed around all of the pulleys.



INSTALLATION

1.

ⓘ CAUTIONS:

- Clean and inspect the accessory drive belt pulleys for damage.
- Ensure the drive belt is correctly seated in all the pulley grooves.

To install, reverse the removal procedure.