

PUBLISHED: 31-JUL-2012
2014.0 RANGE ROVER (LG), 303-05

ACCESSORY DRIVE - V8 N/A 5.0L PETROL/V8 S/C 5.0L PETROL

SUPERCHARGER BELT TENSIONER (G1509491)

REMOVAL AND INSTALLATION

19.46.09	PULLEY - TENSIONER - SUPERCHARGER DRIVE BELT	5000 CC, AJ V8, SUPERCHARGED	0.5	USED WITHINS
----------	---	------------------------------------	-----	-----------------


REMOVAL


NOTE:

Removal steps in this procedure may contain installation details.

1. Refer to: Cooling Fan - V8 S/C 5.0L Petrol (303-03, Removal and Installation).

2.





Torque: 48 Nm

INSTALLATION

1.



CAUTIONS:

- Make sure the supercharger belt is correctly aligned to the pulleys. Failure to follow this instruction may result in damage to the vehicle.
- Clean and inspect the accessory drive belt pulleys for damage.

To install, reverse the removal procedure.