

PUBLISHED: 16-AUG-2012
2015.0 RANGE ROVER (LG), 303-14

ELECTRONIC ENGINE CONTROLS - TDV8 4.4L DIESEL

LEFT EXHAUST GAS TEMPERATURE SENSOR (G1509575)

REMOVAL AND INSTALLATION

18.31.59	EXHAUST GAS TEMPERATURE SENSOR - LH - RENEW	4400 CC, TDV8	0.1	USED WITHINS	
----------	--	------------------	-----	-----------------	--

REMOVAL



WARNING:

Observe due care when working near a hot exhaust system.



NOTE:

Removal steps in this procedure may contain installation details.

1.




WARNING:

Make sure to support the vehicle with axle stands.

Raise and support the vehicle.


2.



3.

⚠ CAUTION:

Make sure that the mating faces are clean and free of foreign material.



Torque: 35 Nm

INSTALLATION

1.



CAUTION:

If accidentally dropped or knocked install a new sensor.



NOTE:

If the original sensor is to be installed, apply lubricant meeting specification ESE-M12A4-A to the thread of the sensor.

To install, reverse the removal procedure.