

2016.0 RANGE ROVER (LG), 303-01

ENGINE - TDV6 3.0L DIESEL - GEN 2/TDV6 3.0L DIESEL

EXHAUST MANIFOLD
CROSS-OVER PIPE (G1875940)

REMOVAL AND INSTALLATION

30.15.29	PIPE - CROSS- OVER - EXHAUST MANIFOLD - RENEW	3000 CC, TDV6, DIESEL, WITH PARTICULATE FILTER, WITH DIESEL EXHAUST FLUID	3.2	USED WITHINS	+
30.15.29	PIPE - CROSS- OVER - EXHAUST MANIFOLD - RENEW	3000 CC, TDV6, WITH PARTICULATE FILTER	2.8	USED WITHINS	+

GENERAL EQUIPMENT

EQUIPMENT NAME
Transmission jack

REMOVAL

CAUTION:

Take care when handling the cross-over pipe as damage to the insulating material may occur.

NOTE:

Some variation in the illustrations may occur, but the essential information is always correct.

1.

WARNING:

Make sure to support the vehicle with axle stands.

Raise and support the vehicle.

2. Refer to: [Exhaust System - Vehicles Without: Diesel Particulate Filter \(DPF\)](#) (309-00A Exhaust System - TDV6 3.0L Diesel, Removal and Installation).


Refer to: [Diesel Particulate Filter - Vehicles With: Diesel Exhaust Fluid](#) (309-00A Exhaust System - TDV6 3.0L Diesel, Removal and Installation).

3. Refer to: [Transmission Support Crossmember - TDV6 3.0L Diesel](#) (502-02 Full Frame and Body Mounting, Removal and Installation).

4.

NOTE:


The transmission is lowered for access.



E119345


- General Equipment: [Transmission jack](#)

5.




E117369


6.



7.




8.



9.

CAUTION:


Discard the nuts.




10.

CAUTION:

Discard the nuts and bolt.




11.



12.

CAUTION:


Discard the studs.



13.

CAUTION:


Discard the studs.



14.

NOTE:

Discard the gasket.




E124137

INSTALLATION

1.

NOTE:

Install new gaskets.




E124137

2.

NOTE:

New exhaust manifold retaining studs must be fitted if the old studs are removed.




E144609

Torque: 13 Nm

3.


NOTE:

New exhaust manifold retaining studs must be fitted if the old studs are removed.



Torque: 13 Nm


4.




5.

CAUTIONS:

- New exhaust manifold nuts and bolt must be fitted.
- Only tighten the nuts finger-tight at this stage.




6.



Check for correct alignment.

Torque: 23 Nm


7.



Check for correct alignment.


Torque: 23 Nm

8.




Torque: 23 Nm

9.




Torque: 23 Nm

10.




11.



Torque: 11 Nm

12.



E124166

General Equipment: [Transmission jack](#)

13. Refer to: [Transmission Support Crossmember - TDV6 3.0L Diesel](#) (502-02 Full Frame and Body Mounting, Removal and Installation).
14. Refer to: [Exhaust System - Vehicles Without: Diesel Particulate Filter \(DPF\)](#) (309-00A Exhaust System - TDV6 3.0L Diesel, Removal and Installation).
Refer to: [Diesel Particulate Filter - Vehicles With: Diesel Exhaust Fluid](#) (309-00A Exhaust System - TDV6 3.0L Diesel, Removal and Installation).