

2016.0 RANGE ROVER (LG), 303-03

ENGINE COOLING - TDV6 3.0L DIESEL - GEN 2/TDV6 3.0L DIESEL

CHARGE AIR RADIATOR - TDV6 3.0L DIESEL - GEN 2

[G1875611]

REMOVAL AND INSTALLATION

26.40.20	RADIATOR - CHARGE AIR - RENEW	3000 CC, TDV6	1.7	USED WITHINS	+
----------	--	------------------	-----	-----------------	---

PART(S)

STEP	REPLACE PART / RENEW PART	PART NAME
Removal Step 3	Renew Part	Retaining clip
Removal Step 8	Renew Part	Retaining clip


REMOVAL

1. Refer to: [Cooling System Partial Draining and Vacuum Filling](#) (303-03C Engine Cooling - V8 N/A 5.0L Petrol/V8 S/C 5.0L Petrol, General Procedures).
2. Refer to: [Front Bumper Cover](#) (501-19 Bumpers, Removal and Installation).

3.


NOTE:

Make sure that new components are installed.




Renew Part: [Retaining clip](#).


4.



5.



6.



Torque: 7 Nm

7.




Torque: 4 Nm

8.

NOTES:

- Make sure that new components are installed.
- Left side shown, right side similar.




Renew Part: [Retaining clip](#).


9.

NOTE:

Do not disassemble further if the component is removed for access only.




10.



Torque: 9 Nm

11.



E178856

Inspect the components and renew if damaged or worn.

INSTALLATION

1. To install, reverse the removal procedure.