

PUBLISHED: 08-DEC-2014
2015.0 RANGE ROVER (LG), 303-03

ENGINE COOLING - TDV8 4.4L DIESEL

COOLANT PUMP (G1509383)

REMOVAL AND INSTALLATION

26.50.01	PUMP - WATER - RENEW	4400 CC, TDV8	1.4	USED WITHINS	
----------	----------------------------	------------------	-----	-----------------	--

REMOVAL



NOTES:

- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.

1.

Disconnect the battery ground cable.

Refer to: [Specifications](#) (501-03 Body Closures, Specifications).


2.

Refer to: [Cooling System Partial Draining and Vacuum Filling](#) (303-03A Engine Cooling - TDV6 3.0L Diesel - Gen 2/TDV6 3.0L Diesel - Gen 1.5, General Procedures).

3.


Refer to: [Left Air Cleaner Outlet Pipe](#) (303-12E Intake Air Distribution and Filtering - TDV8 4.4L Diesel, Removal and Installation).

4.




E142592


5.




E142437

6.






8.





Torque: 10 Nm

9.




10.






12.




Torque: 10 Nm

13.




Torque: 23 Nm


14.



15.



16.



Torque: 23 Nm

INSTALLATION

1. To install reverse the removal procedure.