

PUBLISHED: 10-OCT-2017
2014.0 RANGE ROVER (LG), 303-03

ENGINE COOLING - V8 N/A 5.0L PETROL/V8 S/C 5.0L PETROL

AUXILIARY RADIATOR (G1509390)

REMOVAL AND INSTALLATION

26.40.09	RADIATOR ASSEMBLY - SUPPLEMENTARY - RENEW	5000 CC, AJ V8, SUPERCHARGED	1.8	USED WITHINS
----------	--	------------------------------------	-----	-----------------

REMOVAL



CAUTION:

Before disconnecting any components, make sure the area is clean and free from foreign material. When disconnected all openings must be sealed.



NOTE:

Removal steps in this procedure may contain installation details.

1.



WARNING:

Make sure to support the vehicle with axle stands.

Raise and support the vehicle.


2.

Refer to: Front Bumper Cover (501-19 Bumpers, Removal and Installation).

3.

Refer to: Cooling System Partial Draining and Vacuum Filling (303-03 Engine Cooling - TDV6 3.0L Diesel, General Procedures).

4.




5.

⚠ CAUTION:


Be prepared to collect escaping coolant.

△ NOTE:

RH illustration shown, LH is similar.



E143109




7.




CAUTION:

Make sure that new components are installed.




8.



Torque: 9 Nm

9.



Torque: 5 Nm


10.

⚠ CAUTION:

Make sure that new components are installed.

⚠ NOTE:


Make sure that the locking tangs are installed correctly.




11.

 NOTE:


Do not disassemble further if the component is removed for access only.






Torque: 9 Nm

13.



14.



INSTALLATION

1. To install, reverse the removal procedure.