

PUBLISHED: 21-SEP-2017
2014.0 RANGE ROVER (LG), 303-03

ENGINE COOLING - V8 N/A 5.0L PETROL/V8 S/C 5.0L PETROL


COOLING FAN (G1509393)

REMOVAL AND INSTALLATION

26.25.19	COUPLING UNIT - VISCOUS FAN - RENEW	5000 CC, AJ V8, SUPERCHARGED	0.4	USED WITHINS	
----------	---	------------------------------------	-----	-----------------	--

SPECIAL TOOL(S)

303-114



E46076

303-1142

Viscous Coupling
Wrench

303-1143



E55382

303-1143

Viscous Coupling Holding
Tool

REMOVAL


All vehicles

1. Disconnect the battery ground cable.
Refer to: Specifications (414-00 Battery and Charging System - General Information, Specifications).

Vehicles with supercharger

1. Refer to: Air Cleaner Outlet Pipe T-Connector (303-12 Intake Air Distribution and Filtering - V8 S/C 5.0L Petrol, Removal and Installation).

2.





Vehicles without supercharger

1. Refer to: Air Cleaner Outlet Pipe T-Connector (303-12 Intake Air Distribution and Filtering - V8 N/A 5.0L Petrol, Removal and Installation).

All vehicles


- 1.





E143616


3.




E143621

Torque: 4 Nm

4.



5.




6.



CAUTION:

Extra care must be taken not to damage the inner cooling fan.




Vehicles without supercharger

1.

 NOTES:

- The thread is left handed.
- Always protect the cooling pack elements to prevent accidental damage.



Special Tool(s): 303-1142 , 303-1143


Torque: 65 Nm

Vehicles with supercharger

1.

NOTES:


- The thread is right handed.
- Always protect the cooling pack elements to prevent accidental damage.



Special Tool(s): 303-1142 , 303-1143

Torque: 65 Nm


All vehicles



INSTALLATION

1. To install, reverse the removal procedure.

2.



- Rotate the outer cooling fan by hand in both directions.
- Visually check the inner cooling fan for distortion or impact marks.
- If damaged, the cooling fan assembly must be replaced.