


PUBLISHED: 11-MAY-2011
2015.0 RANGE ROVER (LG), 303-00

ENGINE SYSTEM - GENERAL INFORMATION

CAMSHAFT SURFACE INSPECTION (G61237)

GENERAL PROCEDURES

1.



Inspect camshaft lobes for pitting or damage in the active area. Minor pitting is acceptable outside the active area.