

PUBLISHED: 17-JUN-2014
2015.0 RANGE ROVER (LG), 303-00


ENGINE SYSTEM - GENERAL INFORMATION

CYLINDER HEAD DISTORTION (G1676086)

GENERAL PROCEDURES

CHECK

1.



Using a suitable metallic straight edge and feeler gauge, measure the cylinder head face in the areas illustrated. **Note the maximum value** .

2.



CAUTION:

Machine the **minimum** thickness of material from the cylinder head to meet specification. If a selection of cylinder head gaskets are available, increase the thickness of the cylinder head gasket by one size.



NOTES:

- Prior to having the cylinder head machined, prior approval is required by Jaguar or Land Rover engineering.
- If the cylinder head requires machining, this must be carried out by a local engineering company.

If the cylinder head exceeds the maximum value (0.2mm), the cylinder head must be machined.