

2016.0 RANGE ROVER (LG), 309-00

EXHAUST SYSTEM – TDV6 3.0L DIESEL

DIAGNOSIS AND TESTING

PRINCIPLE OF OPERATION

For a detailed description of the exhaust system, refer to the relevant Description and Operation section of the workshop manual.

REFER to: [Exhaust System](#) (309-00A Exhaust System - TDV6 3.0L Diesel, Description and Operation).

INSPECTION AND VERIFICATION

CAUTION:

Diagnosis by substitution from a donor vehicle is **NOT** acceptable. Substitution of control modules does not guarantee confirmation of a fault and may also cause additional faults in the vehicle being checked and/or the donor vehicle

NOTE:

Check and rectify basic faults before beginning diagnostic routines involving pinpoint tests

1. Verify the customer concern

2. Visually inspect for obvious signs of mechanical or electrical damage

Visual Inspection

MECHANICAL	ELECTRICAL
▪ Leaks ▪ Metal fatigue ▪ Pipes ▪ Catalytic converter ▪ Muffler(s) ▪ Joints ▪ Mountings ▪ Clearance around components	▪ Fuses ▪ Wiring harness ▪ Electrical connector(s) ▪ Sensor(s) ▪ Engine Control Module (ECM)

3. If an obvious cause for an observed or reported concern is found, correct the cause (if possible) before proceeding to the next step

4. If the cause is not visually evident, verify the symptom and refer to the Symptom Chart, alternatively check for DTCs and refer to the DTC Index

SYMPTOM CHART

SYMPTOM	POSSIBLE CAUSES	ACTION
Noisy or leaking exhaust	▪ Exhaust system/components	▪ Install new components as necessary. Refer to the relevant section of the workshop manual
Lack of power	▪ Air intake system fault ▪ Restricted exhaust system ▪ Low fuel pressure ▪ Exhaust Gas	▪ Check the air intake system ▪ Check for a blocked catalytic converter or muffler, install new components as necessary ▪ Check the fuel pressure ▪ For EGR and turbocharger tests, refer to the relevant section of the workshop manual

	Recirculation (EGR) valve(s) fault ▪ Turbocharger fault	
--	--	--

D T C I N D E X

For a complete list of all diagnostic trouble codes that could be logged on this vehicle, please refer to Section 100-00.

REFER to: [Diagnostic Trouble Code Index - TDV6 3.0L Diesel - Gen 1.5](#),
[DTC: Engine Control Module \(ECM\)](#) (100-00 General Information, Description and Operation).