

PUBLISHED: 22-OCT-2013
2015.0 RANGE ROVER (LG), 303-05

ACCESSORY DRIVE - TDV8 4.4L DIESEL

ACCESSORY DRIVE BELT TENSIONER

(G1509479)

REMOVAL AND INSTALLATION

86.10.06	TENSIONER - GENERATOR DRIVE BELT - RENEW	4400 CC, TDV8	0.5	USED WITHINS	
----------	--	------------------	-----	-----------------	--

REMOVAL



NOTES:

- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.

1.


Disconnect the battery ground cable.

Refer to: [Specifications](#) (414-00 Battery and Charging System - General Information, Specifications).

2.


Refer to: [Left Air Cleaner Outlet Pipe](#) (303-12E Intake Air Distribution and Filtering - TDV8 4.4L Diesel, Removal and Installation).

3.





E142592

4.




E142437







7.



8.




9.



10.


⚠ CAUTIONS:

- Make sure that the accessory drive belt is correctly located on each pulley.
- Make sure that the accessory drive belt is correctly routed around all of the pulleys.



E142597

11.



E142598

Torque: 25 Nm

INSTALLATION

1. To install, reverse the removal procedure.