

PUBLISHED: 04-AUG-2012
2015.0 RANGE ROVER (LG), 303-05

ACCESSORY DRIVE - TDV8 4.4L DIESEL

ACCESSORY DRIVE BELT IDLER PULLEY (G1509480)

REMOVAL AND INSTALLATION

86.10.23	JOCKEY PULLEY - GENERATOR DRIVE BELT - RENEW	4400 CC, TDV8	0.6	USED WITHINS	
----------	--	------------------	-----	-----------------	--

REMOVAL



NOTES:

- Removal steps in this procedure may contain installation details.
- Some variation in the illustrations may occur, but the essential information is always correct.

1.


Disconnect the battery ground cable.

Refer to: [Specifications](#) (414-00 Battery and Charging System - General Information, Specifications).

2.


Refer to: [Accessory Drive Belt](#) (303-05D Accessory Drive - TDV8 4.4L Diesel, Removal and Installation).

3.



E142590

4.



E142591

Torque: 62 Nm

INSTALLATION

1. To install, reverse the removal procedure.